Reserve Study Update Sampson Creek Community Development District St. Augustine, Florida



Prepared for FY 2023 Report Date: April 15, 2023





April 15, 2023

Mr. Daniel Laughlin, District Manager GMS 475 West Town Place, Suite 111 St. Augustine, Florida 32092

Re: Sampson Creek Community Development District

Dear Mr. Laughlin:

Community Advisors is pleased to provide this Revised Reserve Study report for the above referenced Association. We have completed the adjustments you requested and have updated your funding plan. We recommend updating your study every 3 years to keep your information current with changing replacement cost, interest and inflation rates.

It has been a pleasure serving you and please let me know if you have any questions or concerns.


Respectively submitted,

CRShamand

Charles R. Sheppard RS PRA CCI

Professional Reserve Analyst

10459 Hunters Creek Court Jacksonville, Fl. 32256









SPECIAL NOTICE

THIS RESERVE ANALYLSIS INCLUDED A VISUAL OBSERVATION OF MAJOR COMPONENTS FOR YOUR PROPERTY. NO DISTRUCTION TESTING OR OTHER TESTING WAS CONDUCTED TO DETERMINE COMPONENT CONDITION. OUR ANALYSIS INCLUDES COMPONENTS WITH REPLACEMENT COST AND USEFUL LIFE PROJECTIONS THAT ARE TYPICAL FOR THIS TYPE OF FACILITY.

THIS ANALYSIS IS NOT A SAFETY INSPECTION OR STRUCTURAL INSPECTION AND WE RECOMMEND THE ASSOCIATION CONDUCT THOSE INSPECTIONS ON A REGULAR BASIS WITH OTHER CONSULTANTS.

TABLE OF CONTENTS

| EXECUTIVE SUMMARY | |
|--|------|
| Executive Summary | 1-1 |
| Financial Summary - Recommended Funding Plan | 1-2 |
| Cash Flow Funding Plan VS Fully Funded | |
| Current Funding Plan vs Recommended Funding Plan | 1-4 |
| CURRENT FUNDING PLAN | |
| Financial Summary - Current Funding Plan | 2-1 |
| Current Funding Plan Projection | |
| CASH FLOW | |
| Income & Expense Spreadsheet | 3-1 |
| EXPENDITURE DETAIL | |
| Annual Expenditure Detail | 4-1 |
| Asset Current Cost by Category | 4-15 |
| COMPONENT INVENTORY | |
| Component Inventory | 5-1 |
| Component Detail Index | 5-4 |
| Component Detail | 5-7 |
| DISCLOSURERS & INFORMATION | |
| Report Navigation | 6-1 |
| Methodology & Information | 6-2 |
| Terms of Service | 6-3 |
| Definitions | 6-4 |

Executive Summary

Account Information

Account Name Sampson Creek Community Development District Account Number 1917

City St. Augustine Last Site Visit April, 4 2023 State Florida Report Date April, 15 2023

In Service Date May, 30 2002 Report Version 2

Total Units 799 Fiscal Year Start October, 1 2023
Study Level I Update Fiscal year End September, 30 2024

Reserve Fund Information

Current Component Replacement Cost \$2,918,673
Number of Components 74
Reserve Fund Beginning Balance \$149,731

Reserve Fund Beginning Balance \$149,731
Billing Term Annually

Component Funding (Straight Line)

Recommended First Year Reserve Fund Contribution \$367,832
Interest Rate on Reserve Deposits 0%
Inflation Rate on Replacement Cost 0%

Pooled Cash (Current Funding Plan)

Current Year Reserve Fund Contribution \$91,562
Interest Rate on Reserve Deposits 4.0%
Inflation Rate on Replacement Cost 3.5%
Annual Contribution Increases 3.0%

Pooled Cash (Recommended Funding Plan)

Recommended First Year Reserve Fund Contribution

Interest Rate on Reserve Deposits

Inflation Rate on Replacement Cost

Annual Contribution Increases

\$205,816

4.0%

3.5%

3.0%

Comments

- Current funding level adequate for future component replacement in FY 2026/2027...
- Recommended funding plan requires larger contributions than budgeted for adequate funding.

Sampson Creek Community Development District Financial Summary - Recommended Funding Plan

Begining Balance: \$149,731 Fully Funded: \$1,238,017 Tax Rate:0%

| | C | U | | | • | . , , | | | | |
|-------|--|-----------|--|--------------|---|----------|---|------------|--------------------------|---|
| | A SON ON THE PROPERTY OF THE P | | And South | idor | | | QUE AND | \$ × | 28 (19) 28 28 (19) 28 | go ~ 1 |
| | ≥ Section (Section) | talaga de | A SO | Other racous | 411 4 40 00 00 00 00 00 00 00 00 00 00 00 0 | | | To Spill | 200 Car. 20 | के की विश्वेत के कि का कि |
| Year | € ₆ X,C ₀ , | All dig | स्या रुंड्य एवर | Other though | 14 5 4 4 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 | So right | 50,54x | Ting Sugar | 76,000,000,000 | 50°0/0× |
| | | | | | | | | | | |
| 23-24 | 2,918,673 | 3.5% | 205,816 | 0 | 4.00% | 12,898 | 33,106 | 335,338 | 1,421,279 | 24% |
| 24-25 | 3,020,827 | 3.5% | 211,990 | 0 | 4.00% | 20,343 | 38,763 | 528,908 | 1,613,339 | 33% |
| 25-26 | 3,126,556 | 3.5% | 218,350 | 0 | 4.00% | 24,305 | 139,645 | 631,917 | 1,714,554 | 37% |
| 26-27 | 3,235,985 | 3.5% | 224,900 | 0 | 4.00% | 18,202 | 401,760 | 473,260 | 1,555,702 | 30% |
| 27-28 | 3,349,245 | 3.5% | 231,647 | 0 | 4.00% | 20,118 | 201,964 | 523,061 | 1,605,795 | 33% |
| 28-29 | 3,466,468 | 3.5% | 238,597 | 0 | 4.00% | 27,996 | 61,760 | 727,894 | 1,810,076 | 40% |
| 29-30 | 3,587,795 | 3.5% | 245,755 | 0 | 4.00% | 20,347 | 464,969 | 529,027 | 1,611,737 | 33% |
| 30-31 | 3,713,368 | 3.5% | 253,127 | 0 | 4.00% | 30,408 | 21,954 | 790,608 | 1,872,659 | 42% |
| 31-32 | 3,843,335 | 3.5% | 260,721 | 0 | 4.00% | 35,534 | 162,987 | 923,876 | 2,004,851 | 46% |
| 32-33 | 3,977,852 | 3.5% | 268,543 | 0 | 4.00% | 45,518 | 54,461 | 1,183,475 | 2,262,231 | 52% |
| 33-34 | 4,117,077 | 3.5% | 276,599 | 0 | 4.00% | 56,119 | 57,101 | 1,459,092 | 2,534,412 | 58% |
| 34-35 | 4,261,175 | 3.5% | 284,897 | 0 | 4.00% | 67,572 | 54,679 | 1,756,882 | 2,827,471 | 62% |
| 35-36 | 4,410,316 | 3.5% | 293,444 | 0 | 4.00% | 79,474 | 63,465 | 2,066,336 | 3,130,828 | 66% |
| 36-37 | 4,564,677 | 3.5% | 302,247 | 0 | 4.00% | 83,499 | 281,099 | 2,170,983 | 3,229,003 | 67% |
| 37-38 | 4,724,441 | 3.5% | 311,315 | 0 | 4.00% | 95,148 | 103,596 | 2,473,849 | 3,524,114 | 70% |
| 38-39 | 4,889,796 | 3.5% | 320,654 | 0 | 4.00% | 109,109 | 66,773 | 2,836,840 | 3,877,792 | 73% |
| 39-40 | 5,060,939 | 3.5% | 330,274 | 0 | 4.00% | 121,180 | 137,606 | 3,150,687 | 4,181,017 | 75% |
| 40-41 | 5,238,072 | 3.5% | 340,182 | 0 | 4.00% | 37,520 | 2,552,873 | 975,516 | 2,005,901 | 49% |
| 41-42 | 5,421,404 | 3.5% | 350,387 | 0 | 4.00% | 14,016 | 975,516 | 364,403 | 1,398,447 | 26% |
| 42-43 | 5,611,153 | 3.5% | 360,899 | 0 | 4.00% | 26,936 | 51,908 | 700,330 | 1,737,287 | 40% |
| 43-44 | 5,807,544 | 3.5% | 371,726 | 0 | 4.00% | 37,788 | 127,346 | 982,498 | 2,021,934 | 49% |
| 44-45 | 6,010,808 | 3.5% | 382,878 | 0 | 4.00% | 52,617 | 49,946 | 1,368,047 | 2,409,101 | 57% |
| 45-46 | 6,221,186 | 3.5% | 394,364 | 0 | 4.00% | 65,357 | 128,488 | 1,699,280 | 2,741,411 | 62% |
| 46-47 | 6,438,928 | 3.5% | 406,195 | 0 | 4.00% | 75,443 | 219,411 | 1,961,507 | 3,004,580 | 65% |
| 47-48 | 6,664,290 | 3.5% | 418,381 | 0 | 4.00% | 82,892 | 307,578 | 2,155,202 | 3,199,509 | 67% |
| 48-49 | 6,897,540 | 3.5% | 430,932 | 0 | 4.00% | 100,496 | 73,733 | 2,612,897 | 3,657,573 | 71% |
| 49-50 | 7,138,954 | 3.5% | 443,860 | 0 | 4.00% | 115,350 | 173,009 | 2,999,099 | 4,043,703 | 74% |
| 50-51 | 7,388,817 | 3.5% | 457,176 | 0 | 4.00% | 134,869 | 84,554 | 3,506,589 | 4,550,200 | 77% |
| 51-52 | 7,647,426 | 3.5% | 470,891 | 0 | 4.00% | 132,230 | 671,719 | 3,437,992 | 4,482,544 | 77% |
| 52-53 | 7,915,086 | 3.5% | 485,018 | 0 | 4.00% | 151,501 | 135,485 | 3,939,025 | 4,983,914 | 79% |
| | | | | | | | | | | |





Chart illustrates year end balances and expenditures with the level of contributions necessary to maintain adequate funding.




This chart illustrates annual expenditures and compares the current funding plan to the recommended funding plan.

Sampson Creek Community Development District Financial Summary - Current Funding Plan

Begining Balance: \$149,731 Fully Funded: \$1,238,017 Tax Rate:0%

| | oji. | | | _ | | | | | | ~ |
|-------|--|---------|------------|-------------|------------------|--|---|--|--|-----------|
| | , ne other | ida | the South | | , _, , | * | | 45 45 18 18 18 18 18 18 18 18 18 18 18 18 18 | 74 (A) 76 | Sp Prints |
| Year | A State of the sta | Taga de | Air So Car | Orac tacous | , the sage | \$ 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 | 40° 20° 20° 10° 10° 10° 10° 10° 10° 10° 10° 10° 1 | 754 59990 | यद्धं द्वीर्य य | 36 King |
| 23-24 | 2,918,673 | 3.5% | 91,562 | 0 | 4.00% | 8,327 | 33,106 | 216,514 | 1,421,279 | 15% |
| 24-25 | 3,020,827 | 3.5% | 94,309 | 0 | 4.00% | 10,882 | 38,763 | 282,943 | 1,613,339 | 18% |
| 25-26 | 3,126,556 | 3.5% | 97,138 | 0 | 4.00% | 9,617 | 139,645 | 250,053 | 1,714,554 | 15% |
| 26-27 | 3,235,985 | 3.5% | 100,052 | 0 | 4.00% | | 401,760 | -51,655 | 1,555,702 | |
| 27-28 | 3,349,245 | 3.5% | 103,054 | 0 | 4.00% | | 201,964 | -150,565 | 1,605,795 | |
| 28-29 | 3,466,468 | 3.5% | 106,145 | 0 | 4.00% | | 61,760 | -106,179 | 1,810,076 | |
| 29-30 | 3,587,795 | 3.5% | 109,330 | 0 | 4.00% | | 464,969 | -461,818 | 1,611,737 | |
| 30-31 | 3,713,368 | 3.5% | 112,610 | 0 | 4.00% | | 21,954 | -371,163 | 1,872,659 | |
| 31-32 | 3,843,335 | 3.5% | 115,988 | 0 | 4.00% | | 162,987 | -418,162 | 2,004,851 | |
| 32-33 | 3,977,852 | 3.5% | 119,468 | 0 | 4.00% | | 54,461 | -353,155 | 2,262,231 | |
| 33-34 | 4,117,077 | 3.5% | 123,052 | 0 | 4.00% | | 57,101 | -287,205 | 2,534,412 | |
| 34-35 | 4,261,175 | 3.5% | 126,743 | 0 | 4.00% | | 54,679 | -215,141 | 2,827,471 | |
| 35-36 | 4,410,316 | 3.5% | 130,546 | 0 | 4.00% | | 63,465 | -148,060 | 3,130,828 | |
| 36-37 | 4,564,677 | 3.5% | 134,462 | 0 | 4.00% | | 281,099 | -294,697 | 3,229,003 | |
| 37-38 | 4,724,441 | 3.5% | 138,496 | 0 | 4.00% | | 103,596 | -259,798 | 3,524,114 | |
| 38-39 | 4,889,796 | 3.5% | 142,651 | 0 | 4.00% | | 66,773 | -183,920 | 3,877,792 | |
| 39-40 | 5,060,939 | 3.5% | 146,930 | 0 | 4.00% | | 137,606 | -174,596 | 4,181,017 | |
| 40-41 | 5,238,072 | 3.5% | 151,338 | 0 | 4.00% | | 2,552,873 | -2,576,131 | 2,005,901 | |
| 41-42 | 5,421,404 | 3.5% | 155,878 | 0 | 4.00% | | 975,516 | -3,395,769 | 1,398,447 | |
| 42-43 | 5,611,153 | 3.5% | 160,555 | 0 | 4.00% | | 51,908 | -3,287,122 | 1,737,287 | |
| 43-44 | 5,807,544 | 3.5% | 165,371 | 0 | 4.00% | | 127,346 | -3,249,098 | 2,021,934 | |
| 44-45 | 6,010,808 | 3.5% | 170,332 | 0 | 4.00% | | 49,946 | -3,128,711 | 2,409,101 | |
| 45-46 | 6,221,186 | 3.5% | 175,442 | 0 | 4.00% | | 128,488 | -3,081,757 | 2,741,411 | |
| 46-47 | 6,438,928 | 3.5% | 180,706 | 0 | 4.00% | | 219,411 | -3,120,463 | 3,004,580 | |
| 47-48 | 6,664,290 | 3.5% | 186,127 | 0 | 4.00% | | 307,578 | -3,241,914 | 3,199,509 | |
| 48-49 | 6,897,540 | 3.5% | 191,710 | 0 | 4.00% | | 73,733 | -3,123,937 | 3,657,573 | |
| 49-50 | 7,138,954 | 3.5% | 197,462 | 0 | 4.00% | | 173,009 | -3,099,483 | 4,043,703 | |
| 50-51 | 7,388,817 | 3.5% | 203,386 | 0 | 4.00% | | 84,554 | -2,980,652 | 4,550,200 | |
| 51-52 | 7,647,426 | 3.5% | 209,487 | 0 | 4.00% | | 671,719 | -3,442,884 | 4,482,544 | |
| 52-53 | 7,915,086 | 3.5% | 215,772 | 0 | 4.00% | | 135,485 | -3,362,598 | 4,983,914 | |



This chart illustrates how the CDD's current funding plan will perform over time.

| | 23-24 | 24-25 | 25-26 | 26-27 | 27-28 | 28-29 | 29-30 | 30-31 | 31-32 | 32-33 |
|---|---------------------------------------|---------------------------------------|--|--|--|---------------------------------------|--|---------------------------------------|--|---|
| Beginning Balance Annual Assessment Interest Earned | 149,731 205,816 12,898 | 335,338 211,990 20,343 | 528,908 218,350 24,305 | 631,917 224,900 18,202 | 473,260 231,647 20,118 | 523,061 238,597 27,996 | 727,894 245,755 20,347 | 529,027 253,127 30,408 | 790,608 260,721 35,534 | 923,876 268,543 45,518 |
| Expenditures Fully Funded Reserves Percent Fully Funded Ending Balance | 33,106 1,421,279 24% 335,338 | 38,763 1,613,339 33% 528,908 | 139,645 1,714,554 37% 631,917 | 401,760 1,555,702 30% 473,260 | 201,964 1,605,795 33% 523,061 | 61,760 1,810,076 40% 727,894 | 464,969 1,611,737 33% 529,027 | 21,954 1,872,659 42% 790,608 | 162,987 2,004,851 46% 923,876 | 54,461 2,262,231 52% 1,183,475 |
| Description Misc. Site Components Monument Sign Refurbishment Allowance | | | | 13,305 | | | | | | |
| Street Signage Allowance Wood Bridge Refurbishment Allowance Misc. Site Components Total: | | | | 13,305 | | | 29,502 29,502 | | 22,122 22,122 | |
| Stormwater System Retention Pond Repair Allowance Street Drainage System Allowance Stormwater System Total: | | | | 33,262 33,262 66,523 | | | 27,002 | | 22,122 | |
| Street Resurfacing Asphalt Mill/Overlay Street Resurfacing Total: | | | | 00,020 | | | | | | |
| Site Concrete Concrete Curb & Gutter Allowance Concrete Sidewalk Allowance Site Concrete Total: | | | 8,570 8,570 17,140 | | | 9,501 9,501 19,003 | | | 10,534 10,534 21,069 | |
| Parking Lot Resurfacing Asphalt Resurfacing 40% - Parking Lot Parking Lot Resurfacing Total: | | | | 92,554 92,554 | | | | | | |

| | 23-24 | 24-25 | 25-26 | 26-27 | 27-28 | 28-29 | 29-30 | 30-31 | 31-32 | 32-33 |
|--|--------|-------|--------|--------|--------|-------|-------|--------|--------|--------|
| Description | | | | | | | | | | |
| Site Lighting | | | | | | | | | | |
| Intersection Light Poles | | | | | 82,622 | | | | | |
| Light Bollards - Parking Lot | | | 5,999 | | | | | | | |
| Light Bollards - Tennis Court Walk | | | | | | | | | | |
| Light Poles - Parking Lot | | | 25,709 | | | | | | | |
| Light Poles - Pool | | | | 29,492 | | | | | | |
| Light Poles - Tennis Courts | | | | 67,854 | | | | | | |
| Site Lighting Total: | | | 31,708 | 97,345 | 82,622 | | | | | |
| Fencing/Gates/Access Control | | | | | | | | | | |
| Access Control Allowance | | | 5,356 | | | | | | | |
| Aluminum Fence - Basketball Court | | | | | | | | | 7,411 | |
| Aluminum Fencing - Pool | | | | 41,118 | | | | | | |
| Chain Link Fence - Tennis Courts | | | | | | | | | 42,454 | |
| Fencing/Gates/Access Control Total: | | | 5,356 | 41,118 | | | | | 49,865 | |
| Landscaping & Irrigation | | | | | | | | | | |
| Irrigation Pumps/Equip. Partial Allowance | 8,000 | | | | | | | | | |
| Landscaping Replacement Allowance | 8,000 | 8,280 | 8,570 | 8,870 | 9,180 | 9,501 | 9,834 | 10,178 | 10,534 | 10,903 |
| Landscaping & Irrigation Total: | 16,000 | 8,280 | 8,570 | 8,870 | 9,180 | 9,501 | 9,834 | 10,178 | 10,534 | 10,903 |
| Building Components | | | | | | | | | | |
| Exterior Door Allowance | | | | | | | | | | |
| Refurbishment Allowance - Pool Restrooms | | | | | 68,851 | | | | | |
| Vinyl Flooring - Aerobics Room | | | | | | | | | | 7,033 |
| Wood Cabinets & Stone Top - Community Room | | | | | | | | | | |
| Building Components Total: | | | | | 68,851 | | | | | 7,033 |
| Roofing | | | | | | | | | | |
| Asphalt Shingles - Fitness Center | | | | | | | | | | 18,808 |
| Asphalt Shingles - Original Buildings | | | 33,508 | | | | | | | |
| Asphalt Shingles - Slide Tower | | | | | | | | | | |
| Roofing Total: | | | 33,508 | | | | | | | 18,808 |

| | 23-24 | 24-25 | 25-26 | 26-27 | 27-28 | 28-29 | 29-30 | 30-31 | 31-32 | 32-33 |
|---|--------|---------|--------|--------|-------|--------|--------|--------------|--------|---------------|
| Description | | | | | | | | | | |
| Furniture Fixtures & Equipment | | | | | | | | | | |
| Audio System | | | | | 4,590 | | | | | |
| Camera System Allowances | | | | | | | 14,751 | | | |
| Fitness Equipment Annual Allowance | | 4,140 | 4,285 | 4,435 | 4,590 | 4,751 | 4,917 | 5,089 | 5,267 | 5,452 |
| Pool/Patio Furniture Full Replace Allowance | | 4 1 4 0 | 4 205 | 4.425 | 0.100 | 4 751 | 10.660 | 5 000 | 5 267 | <i>5 45</i> 2 |
| Furniture Fixtures & Equipment Total: | | 4,140 | 4,285 | 4,435 | 9,180 | 4,751 | 19,668 | 5,089 | 5,267 | 5,452 |
| Painting | | | | | | | | | | |
| Amenity Exterior | 11,106 | | | | | | | | 14,624 | |
| Slide Tower Support Structure | | | | | | | | 2,361 | | |
| Painting Total: | 11,106 | | | | | | | 2,361 | 14,624 | |
| Mechanical Systems | | | | | | | | | | |
| Heat Pump 1 | | | 8,570 | | | | | | | |
| Heat Pump 2 | | 8,280 | | | | | | | | |
| Heat Pump 3 | | 11,592 | | | | | | | | |
| Mechanical Systems Total: | | 19,872 | 8,570 | | | | | | | |
| Tennis Courts | | | | | | | | | | |
| Asphalt Court Resurfacing (Color Coat) | | | 30,508 | | | | | | | |
| Tennis Court Replacement | | | | | | | | | | |
| Tennis Courts Total: | | | 30,508 | | | | | | | |
| Playground | | | | | | | | | | |
| Play Equipment Allowance | | | | 44,349 | | | | | | |
| Shade Structure Frame | | | | | | | | | | |
| Wood Playground Equipment Refurbishment | 6,000 | | | 6,652 | | | 7,376 | | | 8,177 |
| Playground Total: | 6,000 | | | 51,001 | | | 7,376 | | | 8,177 |
| Basketball Courts | | | | | | | | | | |
| Asphalt Resurfacing (Color Coat) | | 6,471 | | | | | 7,686 | | | |
| Basketball Court Replacement | | | | | | | | | | |
| Basketball Poles & Goals | | | | | | 14,252 | | | | |
| Basketball Courts Total: | | 6,471 | | | | 14,252 | 7,686 | | | |

| | 22.24 | 24.25 | 25.26 | 26.27 | 27.20 | 20.20 | 20. 20 | 20.21 | 21 22 | 22.22 |
|--|----------|-------|-------|--------|--------|--------|---------|-------|--------|-------|
| Description | 23-24 | 24-25 | 25-26 | 26-27 | 27-28 | 28-29 | 29-30 | 30-31 | 31-32 | 32-33 |
| Swimming Pool | | | | | | | | | | |
| Concrete Pavers - Pool Deck | | | | | | | | | | |
| Handicap Lift | | | | | | | | 4,326 | | |
| Pool Filtration Refurbishment Allowance | | | | | | | | .,020 | 39,504 | |
| Pool Resurfacing/Tile | | | | | | | 342,225 | | , | |
| Pool Starting Blocks | | | | 13,305 | | | • | | | |
| Refurbishment Allowance - Slide Tower Frame | | | | | 3,443 | | | | | 4,089 |
| Shade Structure Frame | | | | | | 14,252 | | | | |
| Slide Refurbishment Allowance | | | | | 22,950 | | | | | |
| Starting Blocks | | | | 13,305 | | | | | | |
| Swimming Pool Total: | | | | 26,609 | 26,393 | 14,252 | 342,225 | 4,326 | 39,504 | 4,089 |
| Splash Pad | | | | | | | | | | |
| Filtration Refurbishment Allowance | | | | | | | | | | |
| Shade Structure Frame | | | | | | | | | | |
| Splash Pad Play Equipment Allowance | | | | | 5,738 | | | | | |
| Splash Pad ReSurfacing | | | | | | | 48,679 | | | |
| Splash Pad Total: | | | | | 5,738 | | 48,679 | | | |
| Operating Expense | | | | | | | | | | |
| Flooring - Community Room | Unfunded | | | | | | | | | |
| Park Benches | Unfunded | | | | | | | | | |
| Picnic Tables | Unfunded | | | | | | | | | |
| Playground Mulch/Carpet | Unfunded | | | | | | | | | |
| Pool Pumps/Equip Partial Replace | Unfunded | | | | | | | | | |
| Pool/Patio Furniture Partial Replace | Unfunded | | | | | | | | | |
| Sand Volleyball Court/Nets | Unfunded | | | | | | | | | |
| Shade Structures - Tennis Courts | Unfunded | | | | | | | | | |
| Soccer Goals & Nets | Unfunded | | | | | | | | | |
| Splash Pad - Pumps/Equip Partial Replacement | Unfunded | | | | | | | | | |
| Components Not Included | | | | | | | | | | |
| Building Foundations/Frames | Unfunded | | | | | | | | | |
| Pool Shell | Unfunded | | | | | | | | | |
| | | | | | | | | | | |

| | 23-24 | 24-25 | 25-26 | 26-27 | 27-28 | 28-29 | 29-30 | 30-31 | 31-32 | 32-33 |
|-----------------------------------|----------|--------|---------|---------|---------|--------|---------|--------|---------|--------|
| Description | | | | | | | | | | |
| Components Not Included continued | | | | | | | | | | |
| Stormwater Pond Bank Rebuilding | Unfunded | | | | | | | | | |
| Stormwater Pond Dredging | Unfunded | | | | | | | | | |
| Stormwater Pond Structures/Pipe | Unfunded | | | | | | | | | |
| Utility Lines | Unfunded | | | | | | | | | |
| = | | | | | | | | | | |
| Year Total: | 33,106 | 38,763 | 139,645 | 401,760 | 201.964 | 61,760 | 464,969 | 21.954 | 162,987 | 54,461 |

| | 33-34 | 34-35 | 35-36 | 36-37 | 37-38 | 38-39 | 39-40 | 40-41 | 41-42 | 42-43 |
|---------------------------------------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|-----------|
| Beginning Balance | 1,183,475 | 1,459,092 | 1,756,882 | 2,066,336 | 2,170,983 | 2,473,849 | 2,836,840 | 3,150,687 | 975,516 | 364,403 |
| Annual Assessment | 276,599 | 284,897 | 293,444 | 302,247 | 311,315 | 320,654 | 330,274 | 340,182 | 350,387 | 360,899 |
| Interest Earned | 56,119 | 67,572 | 79,474 | 83,499 | 95,148 | 109,109 | 121,180 | 37,520 | 14,016 | 26,936 |
| Expenditures | 57,101 | 54,679 | 63,465 | 281,099 | 103,596 | 66,773 | 137,606 | | 975,516 | 51,908 |
| Fully Funded Reserves | 2,534,412 | 2,827,471 | 3,130,828 | 3,229,003 | 3,524,114 | 3,877,792 | 4,181,017 | 2,005,901 | 1,398,447 | 1,737,287 |
| Percent Fully Funded | 58% | 62% | 66% | 67% | 70% | 73% | 75% | 49% | 26% | 40% |
| Ending Balance | 1,459,092 | 1,756,882 | 2,066,336 | 2,170,983 | 2,473,849 | 2,836,840 | 3,150,687 | 975,516 | 364,403 | 700,330 |
| Description | | | | | | | | | | |
| Misc. Site Components | | | | | | | | | | |
| Monument Sign Refurbishment Allowance | | | | | | 20,104 | | | | |
| Street Signage Allowance | | | | | | | | | | |
| Wood Bridge Refurbishment Allowance | | | | | | | | | | |
| Misc. Site Components Total: | | | | | | 20,104 | | | | |
| Stormwater System | | | | | | | | | | |
| Retention Pond Repair Allowance | | | | | | | | | | |
| Street Drainage System Allowance | | | | | | | | | | |
| Stormwater System Total: | | | | | | | | | | |
| Street Resurfacing | | | | | | | | | | |
| Asphalt Mill/Overlay | | | | | | | | 2,502,622 | | |
| Street Resurfacing Total: | | | | | | | | 2,502,622 | | |
| Site Concrete | | | | | | | | | | |
| Concrete Curb & Gutter Allowance | | 11,680 | | | 12,950 | | | 14,357 | | |
| Concrete Sidewalk Allowance | | 11,680 | | | 12,950 | | | 14,357 | | |
| Site Concrete Total: | | 23,360 | | | 25,899 | | | 28,715 | | |
| Parking Lot Resurfacing | | | | | | | | | | |
| Asphalt Resurfacing 40% - Parking Lot | | | | | | | | | | |
| | | | | | | | | | | |

Parking Lot Resurfacing Total:

| | 33-34 | 34-35 | 35-36 | 36-37 | 37-38 | 38-39 | 39-40 | 40-41 | 41-42 | 42-43 |
|---|--------|--------|--------|--------|--------|--------|--------|--------|--------|--------|
| Description | | | | | | | | | | |
| Site Lighting | | | | | | | | | | |
| Intersection Light Poles | | | | | | | | | | |
| Light Bollards - Parking Lot | | | | | | | | | | |
| Light Bollards - Tennis Court Walk | | | | | | | | | | |
| Light Poles - Parking Lot | | | | | | | | | | |
| Light Poles - Pool | | | | | | | | | | |
| Light Poles - Tennis Courts Site Lighting Total: | | | | | | | | | | |
| Site Lighting Total: | | | | | | | | | | |
| Fencing/Gates/Access Control | | | | | | | | | | |
| Access Control Allowance | | | | | | | | | | |
| Aluminum Fence - Basketball Court | | | | | | | | | | |
| Aluminum Fencing - Pool | | | | | | | | | | |
| Chain Link Fence - Tennis Courts | | | | | | | | | | |
| Fencing/Gates/Access Control Total: | | | | | | | | | | |
| Landscaping & Irrigation | | | | | | | | | | |
| Irrigation Pumps/Equip. Partial Allowance | | | | | | 13,403 | | | | |
| Landscaping Replacement Allowance | 11,285 | 11,680 | 12,089 | 12,512 | 12,950 | 13,403 | 13,872 | 14,357 | 14,860 | 15,380 |
| Landscaping & Irrigation Total: | 11,285 | 11,680 | 12,089 | 12,512 | 12,950 | 26,806 | 13,872 | 14,357 | 14,860 | 15,380 |
| Building Components | | | | | | | | | | |
| Exterior Door Allowance | | | | | 12,950 | | | | | |
| Refurbishment Allowance - Pool Restrooms | | | | | | | | | | |
| Vinyl Flooring - Aerobics Room | | | | | | | | | | |
| Wood Cabinets & Stone Top - Community Room | | 4,672 | | | | | | | | |
| Building Components Total: | | 4,672 | | | 12,950 | | | | | |
| Roofing | | | | | | | | | | |
| Asphalt Shingles - Fitness Center | | | | | | | | | | |
| Asphalt Shingles - Original Buildings | | | | | | | | | | |
| Asphalt Shingles - Slide Tower | | | | | | | | | 11,702 | |
| Roofing Total: | | | | | | | | | 11,702 | |

| | 33-34 | 34-35 | 35-36 | 36-37 | 37-38 | 38-39 | 39-40 | 40-41 | 41-42 | 42-43 |
|---|--------|-------|--------|---------|--------|--------|--------|-------|--------------|-------|
| Description | | | | | | | | | | |
| Furniture Fixtures & Equipment | | | | | | | | | | |
| Audio System | | | 6,044 | | | | | | | |
| Camera System Allowances | | | | | 19,424 | | | | | |
| Fitness Equipment Annual Allowance | 5,642 | 5,840 | 6,044 | 6,256 | 6,475 | 6,701 | 6,936 | 7,179 | 7,430 | 7,690 |
| Pool/Patio Furniture Full Replace Allowance | | 5.040 | 12.000 | () [(| 25 000 | C 701 | 86,699 | 7 170 | 7 420 | 7.000 |
| Furniture Fixtures & Equipment Total: | 5,642 | 5,840 | 12,089 | 6,256 | 25,899 | 6,701 | 93,635 | 7,179 | 7,430 | 7,690 |
| Painting | | | | | | | | | | |
| Amenity Exterior | | | | | | | 19,258 | | | |
| Slide Tower Support Structure | | | | | | 3,109 | | | | |
| Painting Total: | | | | | | 3,109 | 19,258 | | | |
| Mechanical Systems | | | | | | | | | | |
| Heat Pump 1 | | | | | 12,950 | | | | | |
| Heat Pump 2 | | | | 12,512 | | | | | | |
| Heat Pump 3 | | | | 17,516 | | | | | | |
| Mechanical Systems Total: | | | | 30,028 | 12,950 | | | | | |
| Tennis Courts | | | | | | | | | | |
| Asphalt Court Resurfacing (Color Coat) | 40,174 | | | | | | | | 52,901 | |
| Tennis Court Replacement | | | | | | | | | 190,207 | |
| Tennis Courts Total: | 40,174 | | | | | | | | 243,108 | |
| Playground | | | | | | | | | | |
| Play Equipment Allowance | | | | | | | | | 74,300 | |
| Shade Structure Frame | | | | 9,822 | | | | | | |
| Wood Playground Equipment Refurbishment | | | 9,066 | | | 10,052 | | | 11,145 | |
| Playground Total: | | | 9,066 | 9,822 | | 10,052 | | | 85,445 | |
| Basketball Courts | | | | | | | | | | |
| Asphalt Resurfacing (Color Coat) | | 9,128 | | | | | 10,842 | | | |
| Basketball Court Replacement | | | | 53,950 | | | | | | |
| Basketball Poles & Goals | | | | | | | | | | |
| Basketball Courts Total: | | 9,128 | | 53,950 | | | 10,842 | | | |

| | 33-34 | 34-35 | 35-36 | 36-37 | 37-38 | 38-39 | 39-40 | 40-41 | 41-42 | 42-43 |
|--|----------------------|-------|--------|---------|-------|-------|-------|-------|---------|--------|
| Description | | | | | | | | | | |
| Swimming Pool | | | | | | | | | | |
| Concrete Pavers - Pool Deck | | | | 168,532 | | | | | | |
| Handicap Lift | | | | | | | | | | |
| Pool Filtration Refurbishment Allowance Pool Resurfacing/Tile | | | | | | | | | 517,125 | |
| Pool Starting Blocks | | | | | | | | | 22,290 | |
| Refurbishment Allowance - Slide Tower Frame | | | | | 4,856 | | | | 22,270 | 5,768 |
| Shade Structure Frame | | | | | , | | | | | , |
| Slide Refurbishment Allowance | | | 30,221 | | | | | | | |
| Starting Blocks | | | | | | | | | | |
| Swimming Pool Total: | | | 30,221 | 168,532 | 4,856 | | | | 539,415 | 5,768 |
| Splash Pad | | | | | | | | | | |
| Filtration Refurbishment Allowance | | | | | | | | | | |
| Shade Structure Frame | | | | | | | | | | 23,070 |
| Splash Pad Play Equipment Allowance | | | | | 8,093 | | | | 70.557 | |
| Splash Pad ReSurfacing Splash Pad Total: | | | | | 8,093 | | | | 73,557 | 22.070 |
| Spiasii Fau Totai: | | | | | 8,093 | | | | 73,557 | 23,070 |
| Operating Expense | | | | | | | | | | |
| Flooring - Community Room | Unfunded | | | | | | | | | |
| Park Benches | Unfunded | | | | | | | | | |
| Picnic Tables | Unfunded | | | | | | | | | |
| Playground Mulch/Carpet Pool Pumps/Equip Partial Replace | Unfunded Unfunded | | | | | | | | | |
| Pool/Patio Furniture Partial Replace | Unfunded | | | | | | | | | |
| Sand Volleyball Court/Nets | Unfunded | | | | | | | | | |
| Shade Structures - Tennis Courts | Unfunded | | | | | | | | | |
| Soccer Goals & Nets | Unfunded | | | | | | | | | |
| Splash Pad - Pumps/Equip Partial Replacement | Unfunded | | | | | | | | | |
| Components Not Included | | | | | | | | | | |
| Building Foundations/Frames | Unfunded | | | | | | | | | |
| Pool Shell | Unfunded | | | | | | | | | |
| | | | | | | | | | | |

| | 33-34 | 34-35 | 35-36 | 36-37 | 37-38 | 38-39 | 39-40 | 40-41 | 41-42 | 42-43 |
|-----------------------------------|----------|--------|--------|---------|---------|--------|---------|-----------|---------|--------|
| Description | | | | | | | | | | |
| Components Not Included continued | | | | | | | | | | |
| Stormwater Pond Bank Rebuilding | Unfunded | | | | | | | | | |
| Stormwater Pond Dredging | Unfunded | | | | | | | | | |
| Stormwater Pond Structures/Pipe | Unfunded | | | | | | | | | |
| Utility Lines | Unfunded | | | | | | | | | |
| = | | | | | | | | | | |
| Year Total: | 57,101 | 54,679 | 63,465 | 281,099 | 103,596 | 66,773 | 137,606 | 2,552,873 | 975,516 | 51,908 |

| | 43-44 | 44-45 | 45-46 | 46-47 | 47-48 | 48-49 | 49-50 | 50-51 | 51-52 | 52-53 | |
|---------------------------------------|-----------|-----------|-----------|------------------|-----------|-----------|------------------|-----------|-----------|-----------|---|
| Beginning Balance | 700,330 | 982,498 | 1,368,047 | 1,699,280 | 1,961,507 | 2,155,202 | 2,612,897 | 2,999,099 | 3,506,589 | 3,437,992 | |
| Annual Assessment | 371,726 | 382,878 | 394,364 | 406,195 | 418,381 | 430,932 | 443,860 | 457,176 | 470,891 | 485,018 | |
| Interest Earned | 37,788 | 52,617 | 65,357 | 75,443 | 82,892 | 100,496 | 115,350 | 134,869 | 132,230 | 151,501 | |
| Expenditures | 127,346 | 49,946 | 128,488 | 219,411 | 307,578 | 73,733 | 173,009 | 84,554 | 671,719 | 135,485 | |
| Fully Funded Reserves | 2,021,934 | 2,409,101 | 2,741,411 | 3,004,580 | | 3,657,573 | 4,043,703 | 4,550,200 | 4,482,544 | 4,983,914 | |
| Percent Fully Funded | 49% | 57% | 62% | 65% | 67% | 71% | 74% | 77% | 77% | 79% | |
| Ending Balance | 982,498 | 1,368,047 | 1,699,280 | 1,961,507 | 2,155,202 | 2,612,897 | 2,999,099 | 3,506,589 | 3,437,992 | 3,939,025 | |
| Description | | | | | | | | | | | |
| Misc. Site Components | | | | | | | | | | | |
| Monument Sign Refurbishment Allowance | | | | | | | | 30,379 | | | |
| Street Signage Allowance | | | | | | | | | | | |
| Wood Bridge Refurbishment Allowance | | | | | | | | | | | |
| Misc. Site Components Total: | | | | | | | | 30,379 | | | |
| Stormwater System | | | | | | | | | | | |
| Retention Pond Repair Allowance | | | | 66,183 | | | | | | | |
| Street Drainage System Allowance | | | | 66,183 | | | | | | | |
| Stormwater System Total: | | | | 132,367 | | | | | | | _ |
| Street Resurfacing | | | | | | | | | | | |
| Asphalt Mill/Overlay | | | | | | | | | | | |
| Street Resurfacing Total: | | | | | | | | | | | _ |
| Site Concrete | | | | | | | | | | | |
| Concrete Curb & Gutter Allowance | 15,918 | | | 17.640 | | | 10.569 | | | 21,695 | |
| Concrete Sidewalk Allowance | 15,918 | | | 17,649 17,649 | | | 19,568 19,568 | | | 21,695 | |
| Site Concrete Total: | 31,837 | | | 35,298 | | | 39,135 | | | 43,390 | _ |
| | 31,037 | | | 33,490 | | | 37,133 | | | 43,370 | |
| Parking Lot Resurfacing | | | | | | | | | | | |
| Asphalt Resurfacing 40% - Parking Lot | | | | | | | | | 218,728 | | |
| Parking Lot Resurfacing Total: | | | | | | | | | 218,728 | | |

| | 43-44 | 44-45 | 45-46 | 46-47 | 47-48 | 48-49 | 49-50 | 50-51 | 51-52 | 52-53 |
|--|--------|--------|--------|----------|---------|--------|--------|--------|---------|--------|
| Description | | | | | | | | | | |
| Site Lighting | | | | | | | | | | |
| Intersection Light Poles | | | | | | | | | | |
| Light Bollards - Parking Lot | | | | | 12,787 | | | | | |
| Light Bollards - Tennis Court Walk | | | | 21,179 | | | | | | |
| Light Poles - Parking Lot | | | | | 54,800 | | | | | |
| Light Poles - Pool | | | | | | | | | 69,697 | |
| Light Poles - Tennis Courts | | | | | | | | | 160,355 | |
| Site Lighting Total: | | | | 21,179 | 67,587 | | | | 230,051 | |
| Fencing/Gates/Access Control | | | | | | | | | | |
| Access Control Allowance | | | 10,658 | | | | | | | |
| Aluminum Fence - Basketball Court | | | | | | | | | | |
| Aluminum Fencing - Pool | | | | | | | | | 97,172 | |
| Chain Link Fence - Tennis Courts | | | | | | | | | | |
| Fencing/Gates/Access Control Total: | | | 10,658 | | | | | | 97,172 | |
| Landscaping & Irrigation | | | | | | | | | | |
| Irrigation Pumps/Equip. Partial Allowance | | | | | | | | | | |
| Landscaping Replacement Allowance | 15,918 | 16,475 | 17,052 | 17,649 | 18,267 | 18,906 | 19,568 | 20,253 | 20,961 | 21,695 |
| Landscaping & Irrigation Total: | 15,918 | 16,475 | 17,052 | 17,649 | 18,267 | 18,906 | 19,568 | 20,253 | 20,961 | 21,695 |
| Building Components | | | | | | | | | | |
| Exterior Door Allowance | | | | | | | | | | |
| Refurbishment Allowance - Pool Restrooms | | | | | 137,000 | | | | | |
| Vinyl Flooring - Aerobics Room | | | | | | | | | | 13,993 |
| Wood Cabinets & Stone Top - Community Room | | | | | | | | | | |
| Building Components Total: | | | | | 137,000 | | | | | 13,993 |
| Roofing | | | | | | | | | | |
| Asphalt Shingles - Fitness Center | | | | | | | | | | 37,424 |
| Asphalt Shingles - Original Buildings | | | 66,674 | | | | | | | |
| Asphalt Shingles - Slide Tower | | | | | | | | | | |
| Roofing Total: | | | 66,674 | <u> </u> | | | | | | 37,424 |

| | 43-44 | 44-45 | 45-46 | 46-47 | 47-48 | 48-49 | 49-50 | 50-51 | 51-52 | 52-53 |
|---|--------|--------|--------|-------|--------|--------|--------|--------|--------|--------|
| Description | | | | | | | | | | |
| Furniture Fixtures & Equipment | | | | | | | | | | |
| Audio System | 7,959 | | | | | | | | 10,481 | |
| Camera System Allowances | | | 25,578 | | | | | | | |
| Fitness Equipment Annual Allowance | 7,959 | 8,238 | 8,526 | 8,824 | 9,133 | 9,453 | 9,784 | 10,126 | 10,481 | 10,848 |
| Pool/Patio Furniture Full Replace Allowance | | | | | | | | | | |
| Furniture Fixtures & Equipment Total: | 15,918 | 8,238 | 34,104 | 8,824 | 9,133 | 9,453 | 9,784 | 10,126 | 20,961 | 10,848 |
| Painting | | | | | | | | | | |
| Amenity Exterior | | | | | 25,359 | | | | | |
| Slide Tower Support Structure | | | | 4,095 | | | | | | |
| Painting Total: | | | | 4,095 | 25,359 | | | | | |
| Mechanical Systems | | | | | | | | | | |
| Heat Pump 1 | | | | | | | 19,568 | | | |
| Heat Pump 2 | | | | | | 18,906 | , | | | |
| Heat Pump 3 | | | | | | 26,468 | | | | |
| Mechanical Systems Total: | | | | | | 45,374 | 19,568 | | | |
| Tennis Courts | | | | | | | | | | |
| Asphalt Court Resurfacing (Color Coat) | | | | | | | 69,661 | | | |
| Tennis Court Replacement | | | | | | | | | | |
| Tennis Courts Total: | | | | | | | 69,661 | | | |
| Playground | | | | | | | | | | |
| Play Equipment Allowance | | | | | | | | | | |
| Shade Structure Frame | | | | | | | | | | |
| Wood Playground Equipment Refurbishment | | 12,357 | | | 13,700 | | | 15,189 | | |
| Playground Total: | | 12,357 | | | 13,700 | | | 15,189 | | |
| Basketball Courts | | | | | | | | | | |
| Asphalt Resurfacing (Color Coat) | | 12,876 | | | | | 15,293 | | | |
| Basketball Court Replacement | | | | | | | | | | |
| Basketball Poles & Goals | 23,877 | | | | | | | | | |
| Basketball Courts Total: | 23,877 | 12,876 | | | | | 15,293 | | | |

| A3-44 44-45 45-46 46-47 47-48 48-49 49-50 Description Swimming Pool Concrete Pavers - Pool Deck Handicap Lift Pool Filtration Refurbishment Allowance | 50-51 8,607 | 51-52 | 52-53 |
|--|--------------------|--------|-------|
| Concrete Pavers - Pool Deck Handicap Lift | 8,607 | | |
| Concrete Pavers - Pool Deck Handicap Lift | 8,607 | | |
| | 8,607 | | |
| Pool Filtration Refurbishment Allowance | | | |
| | | | |
| Pool Resurfacing/Tile | | | |
| Pool Starting Blocks | | | |
| Refurbishment Allowance - Slide Tower Frame 6,850 | | | 8,136 |
| Shade Structure Frame | | 52 402 | |
| Slide Refurbishment Allowance 39,796 | | 52,403 | |
| Starting Blocks 20.700 | 0.605 | 31,442 | 0.126 |
| Swimming Pool Total: 39,796 6,850 | 8,607 | 83,845 | 8,136 |
| Splash Pad | | | |
| Filtration Refurbishment Allowance 18,267 | | | |
| Shade Structure Frame | | | |
| Splash Pad Play Equipment Allowance 11,417 | | | |
| Splash Pad ReSurfacing | | | |
| Splash Pad Total: 29,683 | | | |
| Operating Expense | | | |
| Flooring - Community Room Unfunded | | | |
| Park Benches Unfunded | | | |
| Picnic Tables Unfunded | | | |
| Playground Mulch/Carpet Unfunded | | | |
| Pool Pumps/Equip Partial Replace Unfunded | | | |
| Pool/Patio Furniture Partial Replace Unfunded | | | |
| Sand Volleyball Court/Nets Unfunded | | | |
| Shade Structures - Tennis Courts Unfunded Unfunded | | | |
| Soccer Goals & Nets Unfunded Salash Pad Dumps (Favin Portial Poplacement Unfunded) | | | |
| Splash Pad - Pumps/Equip Partial Replacement Unfunded | | | |
| Components Not Included | | | |
| Building Foundations/Frames Unfunded | | | |
| Pool Shell Unfunded | | | |

| | 43-44 | 44-45 | 45-46 | 46-47 | 47-48 | 48-49 | 49-50 | 50-51 | 51-52 | 52-53 |
|-----------------------------------|----------|--------|---------|---------|---------|--------|---------|--------|---------|---------|
| Description | | | | | | | | | | |
| Components Not Included continued | | | | | | | | | | |
| Stormwater Pond Bank Rebuilding | Unfunded | | | | | | | | | |
| Stormwater Pond Dredging | Unfunded | | | | | | | | | |
| Stormwater Pond Structures/Pipe | Unfunded | | | | | | | | | |
| Utility Lines | Unfunded | | | | | | | | | |
| Year Total: | 127,346 | 49,946 | 128,488 | 219,411 | 307,578 | 73,733 | 173,009 | 84,554 | 671,719 | 135,485 |

| Description | Expenditures |
|---|-----------------|
| Replacement Year 23-24 | |
| Landscaping & Irrigation | |
| Irrigation Pumps/Equip. Partial Allowance | 8,000 |
| Landscaping Replacement Allowance | 8,000 |
| Painting | |
| Amenity Exterior | 11,106 |
| Playground | |
| Wood Playground Equipment Refurbishment | 6,000 |
| Total for 2023 - 2024 | \$33,106 |
| Replacement Year 24-25 | |
| Landscaping & Irrigation | |
| Landscaping Replacement Allowance | 8,280 |
| Furniture Fixtures & Equipment | |
| Fitness Equipment Annual Allowance | 4,140 |
| Mechanical Systems | |
| Heat Pump 2 | 8,280 |
| Heat Pump 3 | 11,592 |
| Basketball Courts | |
| Asphalt Resurfacing (Color Coat) | 6,471 |
| Total for 2024 - 2025 | \$38,763 |
| Replacement Year 25-26 | |
| Site Concrete | |
| Concrete Curb & Gutter Allowance | 8,570 |
| Concrete Sidewalk Allowance | 8,570 |
| Site Lighting | |
| Light Bollards - Parking Lot | 5,999 |
| Light Poles - Parking Lot | 25,709 |
| Fencing/Gates/Access Control | |
| Access Control Allowance | 5,356 |
| Landscaping & Irrigation | |
| Landscaping Replacement Allowance | 8,570 |
| Roofing | |
| Asphalt Shingles - Original Buildings | 33,508 |
| | |

| Description | Expenditures |
|--|-----------------|
| Replacement Year 25-26 continued | |
| Furniture Fixtures & Equipment | |
| Fitness Equipment Annual Allowance | 4,285 |
| Mechanical Systems | |
| Heat Pump 1 | 8,570 |
| Tennis Courts | 20.700 |
| Asphalt Court Resurfacing (Color Coat) | 30,508 |
| Total for 2025 - 2026 | \$139,645 |
| Replacement Year 26-27 | |
| Misc. Site Components | |
| Monument Sign Refurbishment Allowance | 13,305 |
| Stormwater System | |
| Retention Pond Repair Allowance | 33,262 |
| Street Drainage System Allowance | 33,262 |
| Parking Lot Resurfacing | |
| Asphalt Resurfacing 40% - Parking Lot | 92,554 |
| Site Lighting | • • • • • |
| Light Poles - Pool | 29,492 |
| Light Poles - Tennis Courts | 67,854 |
| Fencing/Gates/Access Control | 41 110 |
| Aluminum Fencing - Pool | 41,118 |
| Landscaping & Irrigation | 0.070 |
| Landscaping Replacement Allowance | 8,870 |
| Furniture Fixtures & Equipment | 4.425 |
| Fitness Equipment Annual Allowance | 4,435 |
| Play Equipment Allowance | 44 240 |
| Play Equipment Allowance Wood Playground Equipment Refurbishment | 44,349 6,652 |
| | 0,032 |
| Swimming Pool Pool Starting Blocks | 13,305 |
| Starting Blocks | 13,305 |
| Total for 2026 - 2027 | |
| 10tai 10f 2020 - 2027 | \$401,760 |

| Description | Expenditures |
|---|---------------------|
| Replacement Year 27-28 | |
| Site Lighting | |
| Intersection Light Poles | 82,622 |
| Landscaping & Irrigation | |
| Landscaping Replacement Allowance | 9,180 |
| Building Components | |
| Refurbishment Allowance - Pool Restrooms | 68,851 |
| Furniture Fixtures & Equipment | |
| Audio System | 4,590 |
| Fitness Equipment Annual Allowance | 4,590 |
| Swimming Pool | |
| Refurbishment Allowance - Slide Tower Frame | 3,443 |
| Slide Refurbishment Allowance | 22,950 |
| Splash Pad | |
| Splash Pad Play Equipment Allowance | 5,738 |
| Total for 2027 - 2028 | \$201,964 |
| Replacement Year 28-29 | |
| Site Concrete | |
| Concrete Curb & Gutter Allowance | 9,501 |
| Concrete Sidewalk Allowance | 9,501 |
| Landscaping & Irrigation | |
| Landscaping Replacement Allowance | 9,501 |
| Furniture Fixtures & Equipment | |
| Fitness Equipment Annual Allowance | 4,751 |
| Basketball Courts | |
| Basketball Poles & Goals | 14,252 |
| Swimming Pool | |
| Shade Structure Frame | 14,252 |
| Total for 2028 - 2029 | \$61,760 |
| Replacement Year 29-30 | |
| Misc. Site Components | |
| Wood Bridge Refurbishment Allowance | 29,502 |
| wood Diage Relationalities Anowalice | 27,502 |

| Description | Expenditures |
|---|-----------------|
| Replacement Year 29-30 continued | |
| Landscaping & Irrigation | |
| Landscaping Replacement Allowance | 9,834 |
| Furniture Fixtures & Equipment | |
| Camera System Allowances | 14,751 |
| Fitness Equipment Annual Allowance | 4,917 |
| Playground | |
| Wood Playground Equipment Refurbishment | 7,376 |
| Basketball Courts | |
| Asphalt Resurfacing (Color Coat) | 7,686 |
| Swimming Pool | |
| Pool Resurfacing/Tile | 342,225 |
| Splash Pad | |
| Splash Pad ReSurfacing | 48,679 |
| Total for 2029 - 2030 | \$464,969 |
| Replacement Year 30-31 | |
| Landscaping & Irrigation | |
| Landscaping Replacement Allowance | 10,178 |
| Furniture Fixtures & Equipment | |
| Fitness Equipment Annual Allowance | 5,089 |
| Painting | |
| Slide Tower Support Structure | 2,361 |
| Swimming Pool | |
| Handicap Lift | 4,326 |
| Total for 2030 - 2031 | \$21,954 |
| Replacement Year 31-32 | |
| Misc. Site Components | |
| Street Signage Allowance | 22,122 |
| Site Concrete | |
| Concrete Curb & Gutter Allowance | 10,534 |
| Concrete Sidewalk Allowance | 10,534 |
| Fencing/Gates/Access Control | |
| Aluminum Fence - Basketball Court | 7,411 |

| Description | Expenditures |
|---|------------------|
| Replacement Year 31-32 continued | 10.151 |
| Chain Link Fence - Tennis Courts | 42,454 |
| Landscaping & Irrigation | 10.524 |
| Landscaping Replacement Allowance | 10,534 |
| Furniture Fixtures & Equipment Fitness Equipment Annual Allowance | 5,267 |
| Painting | 2,207 |
| Amenity Exterior | 14,624 |
| Swimming Pool | |
| Pool Filtration Refurbishment Allowance | 39,504 |
| Total for 2031 - 2032 | \$162,987 |
| Replacement Year 32-33 | |
| Landscaping & Irrigation | |
| Landscaping Replacement Allowance | 10,903 |
| Building Components | |
| Vinyl Flooring - Aerobics Room | 7,033 |
| Roofing | |
| Asphalt Shingles - Fitness Center | 18,808 |
| Furniture Fixtures & Equipment | 5 450 |
| Fitness Equipment Annual Allowance | 5,452 |
| Playground Wood Playground Equipment Defunhishment | 0 177 |
| Wood Playground Equipment Refurbishment | 8,177 |
| Swimming Pool Refurbishment Allowance - Slide Tower Frame | 4,089 |
| | |
| Total for 2032 - 2033 | \$54,461 |
| Replacement Year 33-34 | |
| Landscaping & Irrigation | |
| Landscaping Replacement Allowance | 11,285 |
| Furniture Fixtures & Equipment | |
| Fitness Equipment Annual Allowance | 5,642 |
| Tennis Courts | 40.174 |
| Asphalt Court Resurfacing (Color Coat) | 40,174 |
| Total for 2033 - 2034 | \$57,101 |

| Description | Expenditures |
|--|-----------------|
| Replacement Year 34-35 | |
| Site Concrete | |
| Concrete Curb & Gutter Allowance | 11,680 |
| Concrete Sidewalk Allowance | 11,680 |
| Landscaping & Irrigation | |
| Landscaping Replacement Allowance | 11,680 |
| Building Components | |
| Wood Cabinets & Stone Top - Community Room | 4,672 |
| Furniture Fixtures & Equipment | |
| Fitness Equipment Annual Allowance | 5,840 |
| Basketball Courts | |
| Asphalt Resurfacing (Color Coat) | 9,128 |
| Total for 2034 - 2035 | \$54,679 |
| | |
| Replacement Year 35-36 | |
| Landscaping & Irrigation | 4.000 |
| Landscaping Replacement Allowance | 12,089 |
| Furniture Fixtures & Equipment | |
| Audio System | 6,044 |
| Fitness Equipment Annual Allowance | 6,044 |
| Playground | |
| Wood Playground Equipment Refurbishment | 9,066 |
| Swimming Pool | |
| Slide Refurbishment Allowance | 30,221 |
| Total for 2035 - 2036 | \$63,465 |
| Replacement Year 36-37 | |
| Landscaping & Irrigation | |
| Landscaping Replacement Allowance | 12,512 |
| Furniture Fixtures & Equipment | |
| Fitness Equipment Annual Allowance | 6,256 |
| Mechanical Systems | |
| Heat Pump 2 | 12,512 |
| Heat Pump 3 | 17,516 |

| Description | Expenditures |
|---|--------------|
| Replacement Year 36-37 continued | |
| Playground | |
| Shade Structure Frame | 9,822 |
| Basketball Courts | |
| Basketball Court Replacement | 53,950 |
| Swimming Pool | |
| Concrete Pavers - Pool Deck | 168,532 |
| Total for 2036 - 2037 | \$281,099 |
| Replacement Year 37-38 | |
| Site Concrete | |
| Concrete Curb & Gutter Allowance | 12,950 |
| Concrete Sidewalk Allowance | 12,950 |
| Landscaping & Irrigation | |
| Landscaping Replacement Allowance | 12,950 |
| Building Components | |
| Exterior Door Allowance | 12,950 |
| Furniture Fixtures & Equipment | 40.404 |
| Camera System Allowances | 19,424 |
| Fitness Equipment Annual Allowance | 6,475 |
| Mechanical Systems | 12.050 |
| Heat Pump 1 | 12,950 |
| Swimming Pool | 4.056 |
| Refurbishment Allowance - Slide Tower Frame | 4,856 |
| Splash Pad Play Favingment Allower as | 0.002 |
| Splash Pad Play Equipment Allowance | 8,093 |
| Total for 2037 - 2038 | \$103,596 |
| Replacement Year 38-39 | |
| Misc. Site Components | |
| Monument Sign Refurbishment Allowance | 20,104 |
| Landscaping & Irrigation | |
| Irrigation Pumps/Equip. Partial Allowance | 13,403 |
| Landscaping Replacement Allowance | 13,403 |

| Description | Expenditures |
|---|------------------|
| Replacement Year 38-39 continued | |
| Furniture Fixtures & Equipment | |
| Fitness Equipment Annual Allowance | 6,701 |
| Painting | |
| Slide Tower Support Structure | 3,109 |
| Playground | |
| Wood Playground Equipment Refurbishment | 10,052 |
| Total for 2038 - 2039 | \$66,773 |
| Replacement Year 39-40 | |
| Landscaping & Irrigation | |
| Landscaping Replacement Allowance | 13,872 |
| Furniture Fixtures & Equipment | |
| Fitness Equipment Annual Allowance | 6,936 |
| Pool/Patio Furniture Full Replace Allowance | 86,699 |
| Painting | |
| Amenity Exterior | 19,258 |
| Basketball Courts | |
| Asphalt Resurfacing (Color Coat) | 10,842 |
| Total for 2039 - 2040 | \$137,606 |
| Replacement Year 40-41 | |
| Street Resurfacing | |
| Asphalt Mill/Overlay | 2,502,622 |
| Site Concrete | |
| Concrete Curb & Gutter Allowance | 14,357 |
| Concrete Sidewalk Allowance | 14,357 |
| Landscaping & Irrigation | |
| Landscaping Replacement Allowance | 14,357 |
| Furniture Fixtures & Equipment | |
| Fitness Equipment Annual Allowance | 7,179 |
| Total for 2040 - 2041 | \$2,552,873 |
| Replacement Year 41-42 | |
| Landscaping & Irrigation | |
| Landscaping Replacement Allowance | 14,860 |

| Description | Expenditures |
|---|-----------------|
| Replacement Year 41-42 continued | |
| Roofing | |
| Asphalt Shingles - Slide Tower | 11,702 |
| Furniture Fixtures & Equipment | |
| Fitness Equipment Annual Allowance | 7,430 |
| Tennis Courts | |
| Asphalt Court Resurfacing (Color Coat) | 52,901 |
| Tennis Court Replacement | 190,207 |
| Playground | |
| Play Equipment Allowance | 74,300 |
| Wood Playground Equipment Refurbishment | 11,145 |
| Swimming Pool | |
| Pool Resurfacing/Tile | 517,125 |
| Pool Starting Blocks | 22,290 |
| Splash Pad | |
| Splash Pad ReSurfacing | 73,557 |
| Total for 2041 - 2042 | \$975,516 |
| Replacement Year 42-43 | |
| Landscaping & Irrigation | |
| Landscaping Replacement Allowance | 15,380 |
| Furniture Fixtures & Equipment | |
| Fitness Equipment Annual Allowance | 7,690 |
| Swimming Pool | |
| Refurbishment Allowance - Slide Tower Frame | 5,768 |
| Splash Pad | |
| Shade Structure Frame | 23,070 |
| Total for 2042 - 2043 | \$51,908 |
| Replacement Year 43-44 | |
| Site Concrete | |
| Concrete Curb & Gutter Allowance | 15,918 |
| Concrete Sidewalk Allowance | 15,918 |
| Landscaping & Irrigation | |
| Landscaping Replacement Allowance | 15,918 |
| | |

| Description | Expenditures |
|---|-----------------|
| Replacement Year 43-44 continued | |
| Furniture Fixtures & Equipment | |
| Audio System | 7,959 |
| Fitness Equipment Annual Allowance | 7,959 |
| Basketball Courts Basketball Poles & Goals | 23,877 |
| Swimming Pool | |
| Slide Refurbishment Allowance | 39,796 |
| Total for 2043 - 2044 | \$127,346 |
| Replacement Year 44-45 | |
| Landscaping & Irrigation | |
| Landscaping Replacement Allowance | 16,475 |
| Furniture Fixtures & Equipment | 0.000 |
| Fitness Equipment Annual Allowance | 8,238 |
| Playground | 10.257 |
| Wood Playground Equipment Refurbishment | 12,357 |
| Basketball Courts Asphalt Resurfacing (Color Coat) | 12,876 |
| , | |
| Total for 2044 - 2045 | \$49,946 |
| Replacement Year 45-46 | |
| Fencing/Gates/Access Control | |
| Access Control Allowance | 10,658 |
| Landscaping & Irrigation | |
| Landscaping Replacement Allowance | 17,052 |
| Roofing | |
| Asphalt Shingles - Original Buildings | 66,674 |
| Furniture Fixtures & Equipment | 25 579 |
| Camera System Allowances Fitness Equipment Annual Allowance | 25,578 8,526 |
| • • | |
| Total for 2045 - 2046 | \$128,488 |
| Replacement Year 46-47 | |
| Stormwater System | |
| Retention Pond Repair Allowance | 66,183 |

| Description | Expenditures |
|--|--------------|
| Replacement Year 46-47 continued | |
| Street Drainage System Allowance | 66,183 |
| Site Concrete | 4= -40 |
| Concrete Curb & Gutter Allowance Concrete Sidewalk Allowance | 17,649 |
| | 17,649 |
| Site Lighting Light Bollards - Tennis Court Walk | 21,179 |
| Landscaping & Irrigation | |
| Landscaping Replacement Allowance | 17,649 |
| Furniture Fixtures & Equipment | |
| Fitness Equipment Annual Allowance | 8,824 |
| Painting | |
| Slide Tower Support Structure | 4,095 |
| Total for 2046 - 2047 | \$219,411 |
| Replacement Year 47-48 | |
| Site Lighting | |
| Light Bollards - Parking Lot | 12,787 |
| Light Poles - Parking Lot | 54,800 |
| Landscaping & Irrigation | |
| Landscaping Replacement Allowance | 18,267 |
| Building Components | 127.000 |
| Refurbishment Allowance - Pool Restrooms | 137,000 |
| Furniture Fixtures & Equipment | 0.122 |
| Fitness Equipment Annual Allowance | 9,133 |
| Painting Amenity Exterior | 25,359 |
| Playground | 23,337 |
| Wood Playground Equipment Refurbishment | 13,700 |
| Swimming Pool | |
| Refurbishment Allowance - Slide Tower Frame | 6,850 |
| Splash Pad | |
| Filtration Refurbishment Allowance | 18,267 |
| Splash Pad Play Equipment Allowance | 11,417 |
| Total for 2047 - 2048 | \$307,578 |

Sampson Creek Community Development District Annual Expenditure Detail


| Description | Expenditures |
|---|------------------|
| Replacement Year 48-49 | |
| Landscaping & Irrigation | |
| Landscaping Replacement Allowance | 18,906 |
| Furniture Fixtures & Equipment | |
| Fitness Equipment Annual Allowance | 9,453 |
| Mechanical Systems | |
| Heat Pump 2 | 18,906 |
| Heat Pump 3 | 26,468 |
| Total for 2048 - 2049 | \$73,733 |
| Replacement Year 49-50 | |
| Site Concrete | |
| Concrete Curb & Gutter Allowance | 19,568 |
| Concrete Sidewalk Allowance | 19,568 |
| Landscaping & Irrigation | |
| Landscaping Replacement Allowance | 19,568 |
| Furniture Fixtures & Equipment | |
| Fitness Equipment Annual Allowance | 9,784 |
| Mechanical Systems | |
| Heat Pump 1 | 19,568 |
| Tennis Courts | |
| Asphalt Court Resurfacing (Color Coat) | 69,661 |
| Basketball Courts | |
| Asphalt Resurfacing (Color Coat) | 15,293 |
| Total for 2049 - 2050 | \$173,009 |
| Replacement Year 50-51 | |
| Misc. Site Components | |
| Monument Sign Refurbishment Allowance | 30,379 |
| Landscaping & Irrigation | |
| Landscaping Replacement Allowance | 20,253 |
| Furniture Fixtures & Equipment | |
| Fitness Equipment Annual Allowance | 10,126 |
| Playground | |
| Wood Playground Equipment Refurbishment | 15,189 |
| | |

Sampson Creek Community Development District Annual Expenditure Detail

| Description | Expenditures |
|---------------------------------------|--------------|
| Replacement Year 50-51 continued | |
| Swimming Pool | |
| Handicap Lift | 8,607 |
| Total for 2050 - 2051 | \$84,554 |
| Replacement Year 51-52 | |
| Parking Lot Resurfacing | |
| Asphalt Resurfacing 40% - Parking Lot | 218,728 |
| Site Lighting | |
| Light Poles - Pool | 69,697 |
| Light Poles - Tennis Courts | 160,355 |
| Fencing/Gates/Access Control | |
| Aluminum Fencing - Pool | 97,172 |
| Landscaping & Irrigation | |
| Landscaping Replacement Allowance | 20,961 |
| Furniture Fixtures & Equipment | |
| Audio System | 10,481 |
| Fitness Equipment Annual Allowance | 10,481 |
| Swimming Pool | |
| Slide Refurbishment Allowance | 52,403 |
| Starting Blocks | 31,442 |
| Total for 2051 - 2052 | \$671,719 |
| Replacement Year 52-53 | |
| Site Concrete | |
| Concrete Curb & Gutter Allowance | 21,695 |
| Concrete Sidewalk Allowance | 21,695 |
| Landscaping & Irrigation | |
| Landscaping Replacement Allowance | 21,695 |
| Building Components | |
| Vinyl Flooring - Aerobics Room | 13,993 |
| Roofing | |
| Asphalt Shingles - Fitness Center | 37,424 |
| Furniture Fixtures & Equipment | |
| Fitness Equipment Annual Allowance | 10,848 |

Sampson Creek Community Development District Annual Expenditure Detail

| Total for 2052 - 2053 | \$135,485 |
|---|--------------|
| Refurbishment Allowance - Slide Tower Frame | 8,136 |
| Swimming Pool | |
| Replacement Year 52-53 continued | |
| Description | Expenditures |



| | | otto | X | | aedi. | ist ^{re} o | | *. |
|---|--|--|--|----------------------------|-----------------------------|--|--|--|
| Description | ्व : हैं ज़िंदु | S S S S S S S S S S S S S S S S S S S | ا الم | | Sed Sar | pitines Sities | JA OS | CHIC |
| Misc. Site Components Monument Sign Refurbishment Allowance Street Signage Allowance Wood Bridge Refurbishment Allowance Misc. Site Components - Total | 2015 2002 2002 | 26-27 31-32 29-30 | 12 25 25 | 0 5 3 | 3 8 6 | 1 Lump Sum 14 Each 1 Lump Sum | 12,000.00 1,200.00 24,000.00 | 12,000 16,800 <u>24,000</u> \$52,800 |
| Stormwater System Retention Pond Repair Allowance Street Drainage System Allowance Stormwater System - Total | 2002 2002 | 26-27 26-27 | 20 20 | 5 5 | 3 3 | 1 Each 1 Lump Sum | 30,000.00 30,000.00 | 30,000 <u>30,000</u> \$60,000 |
| Street Resurfacing Asphalt Mill/Overlay Street Resurfacing - Total | 2020 | 40-41 | 20 | 0 | 17 | 108,943 Square Yards | 12.80 | 1,394,470 \$1,394,470 |
| Site Concrete Concrete Curb & Gutter Allowance Concrete Sidewalk Allowance Site Concrete - Total | 2023 2023 | 25-26 25-26 | 3 3 | 0 | 2 2 | 1 Lump Sum 1 Lump Sum | 8,000.00 8,000.00 | 8,000 <u>8,000</u> \$16,000 |
| Parking Lot Resurfacing Asphalt Resurfacing 40% - Parking Lot Parking Lot Resurfacing - Total | 2002 | 26-27 | 25 | 0 | 3 | 5,153 Square Yards | 16.20 | 83,479 \$83,479 |
| Site Lighting Intersection Light Poles Light Bollards - Parking Lot Light Bollards - Tennis Court Walk Light Poles - Parking Lot Light Poles - Pool Light Poles - Tennis Courts Site Lighting - Total | 2002 2002 2021 2002 2002 2002 | 27-28 25-26 46-47 25-26 26-27 26-27 | 26 22 25 22 25 25 25 25 | 0 2 0 2 0 0 | 4 2 23 2 3 3 | 18 Each 10 Each 8 Each 20 Each 7 Each 18 Each | 4,000.00 1,400.00@ 40 1,200.00 3,000.00@ 40 3,800.00 3,400.00 | 9,600 |
| Fencing/Gates/Access Control Access Control Allowance Aluminum Fence - Basketball Court Aluminum Fencing - Pool Chain Link Fence - Tennis Courts Fencing/Gates/Access Control - Total | 2002 2002 2002 2002 | 25-26 31-32 26-27 31-32 | 20 30 25 30 | 4 0 0 0 | 2 8 3 8 | 1 Each 134 Linear Feet 883 LFT 1,040 Linear Feet | 5,000.00 42.00 42.00 31.00 | 5,000 5,628 37,086 32,240 \$79,954 |
| Landscaping & Irrigation Irrigation Pumps/Equip. Partial Allowance Landscaping Replacement Allowance Landscaping & Irrigation - Total | 2002 2018 | 23-24 23-24 | 15 1 | 0 | 0 0 | 1 Lump Sum 1 Lump Sum | 8,000.00 8,000.00 | 8,000 <u>8,000</u> \$16,000 |

| | | ages | ¢. | | eri . | . <u>1</u> 100 | | |
|---|----------------------|---|--------------------|---------|---------------|---------------------------------------|-----------|-------------------------|
| Description | 04 05 15 04 05 15 | 4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 | य ^{ुर्धी} | , digit | Sellig Ed. | jū ^{to} Si ^{tis} | Jit Ost | |
| Building Components | | | | | | | | |
| Exterior Door Allowance | 2012 | 37-38 | 25 | 0 | 14 | 1 Lump Sum | 8,000.00 | 8,000 |
| Refurbishment Allowance - Pool Restrooms | 2002 | 27-28 | 20 | 6 | 4 | 1 Lump Sum | 60,000.00 | 60,000 |
| Vinyl Flooring - Aerobics Room | 2012 | 32-33 | 20 | 0 | 9 | 600 Square Feet | 8.60 | 5,160 |
| Wood Cabinets & Stone Top - Community Building Components - Total | 2012 | 34-35 | 20 | 2 | 11 | 8 Linear Feet | 400.00 | 3,200 \$76,360 |
| Roofing | | | | | | | | |
| Asphalt Shingles - Fitness Center | 2012 | 32-33 | 20 | 0 | 9 | 30 Squares | 460.00 | 13,800 |
| Asphalt Shingles - Original Buildings | 2002 | 25-26 | 20 | 4 | 2 | 68 Squares | 460.00 | 31,280 |
| Asphalt Shingles - Slide Tower Roofing - Total | 2022 | 41-42 | 20 | 0 | 18 | 9 Squares | 700.00 | $\frac{6,300}{$51,380}$ |
| Furniture Fixtures & Equipment | | | | | | | | |
| Audio System | 2020 | 27-28 | 8 | 0 | 4 | 1 Lump Sum | 4,000.00 | 4,000 |
| Camera System Allowances | 2022 | 29-30 | 8 | 0 | 6 | 1 Lump Sum | 12,000.00 | 12,000 |
| Fitness Equipment Annual Allowance | 2023 | 24-25 | 1 | 1 | 1 | 1 Lump Sum | 4,000.00 | 4,000 |
| Pool/Patio Furniture Full Replace Allowance | 2015 | 39-40 | 25 | 0 | 16 | 1 Lump Sum | 50,000.00 | _50,000 |
| Furniture Fixtures & Equipment - Total | | | | | | | | \$70,000 |
| Painting | | | | | | | | |
| Amenity Exterior | 2012 | 23-24 | 8 | 0 | 0 | 6,170 Square Feet | 1.80 | 11,106 |
| Slide Tower Support Structure Painting - Total | 2023 | 30-31 | 8 | 0 | 7 | 1 Lump Sum | 1,856.00 | 1,856 \$12,962 |
| Mechanical Systems | | | | | | | | |
| Heat Pump 1 | 2013 | 25-26 | 12 | 0 | 2 | 5 Tons | 1,600.00 | 8,000 |
| Heat Pump 2 | 2012 | 24-25 | 12 | 0 | 1 | 5 Tons | 1,600.00 | 8,000 |
| Heat Pump 3 | 2012 | 24-25 | 12 | 0 | 1 | 7 Tons | 1,600.00 | 11,200 |
| Mechanical Systems - Total | | | | | | | | \$27,200 |
| Tennis Courts | | | | | | | | |
| Asphalt Court Resurfacing (Color Coat) | 2018 | 25-26 | 8 | 0 | 2 | 3,200 Square Yards | 8.90 | 28,480 |
| Tennis Court Replacement Tennis Courts - Total | 2002 | 41-42 | 40 | 0 | 18 | 3,200 Square Yards | 32.00 | 102,400 \$130,880 |
| Playground | | | | | | | | |
| Play Equipment Allowance | 2012 | 26-27 | 15 | 0 | 3 | 1 Lump Sum | 40,000.00 | 40,000 |
| Shade Structure Frame | 2012 | 36-37 | 25 | 0 | 13 | 1 Each | 6,280.00 | 6,280 |
| Wood Playground Equipment Refurbishment Playground - Total | 2015 | 23-24 | 3 | 0 | 0 | 1 Lump Sum | 6,000.00 | $\frac{6,000}{$52,280}$ |
| Basketball Courts | | | | | | | | |
| Asphalt Resurfacing (Color Coat) | 2020 | 24-25 | 5 | 0 | 1 | 1,078 Square Yards | 5.80 | 6,252 |

| | | Z.S. | > | | eri | . 550 | | |
|---|-------------|--|-------------|--------|---------|--------------------|-----------|-----------|
| D | Oge Service | 2 40 75 45 45 45 45 45 45 45 45 45 45 45 45 45 | ر پیچین | \$ 68° | A Sugar | gar Light | Jär Os | Cata Ca |
| Description | 2, % | \$ 70 | 2, | S. | \$ | Ø, | \$ 0 | 0,0 |
| Basketball Courts continued | | | | | | | | |
| Basketball Court Replacement | 2002 | 36-37 | 35 | 0 | 13 | 1,078 Square Yards | 32.00 | 34,496 |
| Basketball Poles & Goals | 2012 | 28-29 | 15 | 2 | 5 | 4 Each | 3,000.00 | 12,000 |
| Basketball Courts - Total | | | | | | | | \$52,748 |
| a | | | | | | | | |
| Swimming Pool | | | | | | | | |
| Concrete Pavers - Pool Deck | 2002 | 36-37 | 35 | 0 | 13 | 13,470 Square Feet | 8.00 | 107,760 |
| Handicap Lift | 2011 | 30-31 | 20 | 0 | 7 | 1 Each | 3,400.00 | 3,400 |
| Pool Filtration Refurbishment Allowance | 2002 | 31-32 | 30 | 0 | 8 | 1 Lump Sum | 30,000.00 | 30,000 |
| Pool Resurfacing/Tile | 2018 | 29-30 | 12 | 0 | 6 | 8,700 Square Feet | 32.00 | 278,400 |
| Pool Starting Blocks | 2002 | 26-27 | 15 | 10 | 3 | 6 Each | 2,000.00 | 12,000 |
| Refurbishment Allowance - Slide Tower Fra | 2022 | 27-28 | 5 | 0 | 4 | 1 Each | 3,000.00 | 3,000 |
| Shade Structure Frame | 2002 | 28-29 | 25 | 2 | 5 | 2 Each | 6,000.00 | 12,000 |
| Slide Refurbishment Allowance | 2020 | 27-28 | 8 | 0 | 4 | 1 Lump Sum | 20,000.00 | 20,000 |
| Starting Blocks | 2002 | 26-27 | 25 | 0 | 3 | 6 Each | 2,000.00 | 12,000 |
| Swimming Pool - Total | | | | | | | | \$478,560 |
| | | | | | | | | |
| Splash Pad | | | | | | | | |
| Filtration Refurbishment Allowance | 2018 | 47-48 | 30 | 0 | 24 | 1 Lump Sum | 8,000.00 | 8,000 |
| Shade Structure Frame | 2018 | 42-43 | 25 | 0 | 19 | 2 Each | 6,000.00 | 12,000 |
| Splash Pad Play Equipment Allowance | 2018 | 27-28 | 10 | 0 | 4 | 1 Lump Sum | 5,000.00 | 5,000 |
| Splash Pad ReSurfacing | 2018 | 29-30 | 12 | 0 | 6 | 1,800 Square Feet | 22.00 | 39,600 |
| Splash Pad - Total | | | | | | | | \$64,600 |
| O | | | | | | | | |

Operating Expense

| Sperating Expense | |
|---|----------|
| Flooring - Community Room | Unfunded |
| Park Benches | Unfunded |
| Picnic Tables | Unfunded |
| Playground Mulch/Carpet | Unfunded |
| Pool Pumps/Equip Partial Replace | Unfunded |
| Pool/Patio Furniture Partial Replace | Unfunded |
| Sand Volleyball Court/Nets | Unfunded |
| Shade Structures - Tennis Courts | Unfunded |
| Soccer Goals & Nets | Unfunded |
| Splash Pad - Pumps/Equip Partial Replacem | Unfunded |
| Operating Expense - Total | |
| | |

Components Not Included

| Building Foundations/Frames | Unfunded |
|---------------------------------|----------|
| Pool Shell | Unfunded |
| Stormwater Pond Bank Rebuilding | Unfunded |
| Stormwater Pond Dredging | Unfunded |
| Stormwater Pond Structures/Pipe | Unfunded |
| Utility Lines | Unfunded |
| Components Not Included - Total | - |
| | |

Total Asset Summary \$2,918,673

| Asset II | DDescription | Replacement | Page |
|----------|--|-------------|--------------|
| Misc S | Site Components | | |
| 1030 | Monument Sign Refurbishment Allowance | 26-27 | 5-7 |
| 1027 | Street Signage Allowance | 31-32 | 5-7 |
| 1028 | Wood Bridge Refurbishment Allowance | 29-30 | 5-8 |
| 1020 | Wood Bridge Relazoisiment I mo wante | 27 30 | 2 0 |
| Stormy | vater System | | |
| 1085 | Retention Pond Repair Allowance | 26-27 | 5-9 |
| 1084 | Street Drainage System Allowance | 26-27 | 5-9 |
| C4 | Dogwyfo ein e | | |
| 1075 | Resurfacing Asphalt Mill/Overlay | 40-41 | 5-10 |
| 1073 | Aspiiait Will/Overlay | 40-41 | 3-10 |
| Site Co | oncrete | | |
| 1083 | Concrete Curb & Gutter Allowance | 25-26 | 5-11 |
| 1082 | Concrete Sidewalk Allowance | 25-26 | 5-11 |
| | | | |
| | g Lot Resurfacing | | |
| 1022 | Asphalt Resurfacing 40% - Parking Lot | 26-27 | 5-12 |
| Site Li | ghting | | |
| 1029 | Intersection Light Poles | 27-28 | 5-13 |
| 1023 | Light Bollards - Parking Lot | 25-26 | 5-13 |
| 1051 | Light Bollards - Tennis Court Walk | 46-47 | 5-13 |
| 1024 | Light Poles - Parking Lot | 25-26 | 5-14 |
| 1008 | Light Poles - Pool | 26-27 | 5-14 |
| 1055 | Light Poles - Tennis Courts | 26-27 | 5-15 |
| | | | |
| | g/Gates/Access Control | 25.26 | 5 16 |
| 1041 | Access Control Allowance | 25-26 | 5-16 |
| 1090 | Aluminum Fence - Basketball Court | 31-32 | 5-16 5-16 |
| 1009 | Aluminum Fencing - Pool Chain Link Fence - Tennis Courts | 26-27 | 5-16 5-17 |
| 1052 | Chain Link Fence - Tennis Courts | 31-32 | 5-17 |
| Landso | caping & Irrigation | | |
| 1025 | Irrigation Pumps/Equip. Partial Allowance | 23-24 | 5-18 |
| 1026 | Landscaping Replacement Allowance | 23-24 | 5-18 |
| | | | |
| | ng Components | 25.22 | = 40 |
| 1001 | Exterior Door Allowance | 37-38 | 5-19 |

| Asset II | DDescription | Replacement | Page |
|----------|---|-------------|------|
| Buildin | g Components Continued | | |
| 1086 | Refurbishment Allowance - Pool Restrooms | 27-28 | 5-19 |
| 1070 | Vinyl Flooring - Aerobics Room | 32-33 | 5-20 |
| 1071 | Wood Cabinets & Stone Top - Community Room | 34-35 | 5-20 |
| Roofin | g | | |
| 1033 | Asphalt Shingles - Fitness Center | 32-33 | 5-22 |
| 1031 | Asphalt Shingles - Original Buildings | 25-26 | 5-22 |
| 1032 | Asphalt Shingles - Slide Tower | 41-42 | 5-23 |
| Furnit | ıre Fixtures & Equipment | | |
| 1091 | Audio System | 27-28 | 5-24 |
| 1040 | Camera System Allowances | 29-30 | 5-24 |
| 1035 | Fitness Equipment Annual Allowance | 24-25 | 5-24 |
| 1093 | Pool/Patio Furniture Full Replace Allowance | 39-40 | 5-24 |
| Paintin | g | | |
| 1046 | Amenity Exterior | 23-24 | 5-26 |
| 1047 | Slide Tower Support Structure | 30-31 | 5-26 |
| Mecha | nical Systems | | |
| 1048 | Heat Pump 1 | 25-26 | 5-27 |
| 1050 | Heat Pump 2 | 24-25 | 5-27 |
| 1049 | Heat Pump 3 | 24-25 | 5-27 |
| Tennis | Courts | | |
| 1053 | Asphalt Court Resurfacing (Color Coat) | 25-26 | 5-28 |
| 1097 | Tennis Court Replacement | 41-42 | 5-28 |
| Playgro | ound | | |
| 1062 | Play Equipment Allowance | 26-27 | 5-29 |
| 1059 | Shade Structure Frame | 36-37 | 5-29 |
| 1064 | Wood Playground Equipment Refurbishment | 23-24 | 5-30 |
| Basket | ball Courts | | |
| 1057 | Asphalt Resurfacing (Color Coat) | 24-25 | 5-31 |
| 1099 | Basketball Court Replacement | 36-37 | 5-31 |
| 1058 | Basketball Poles & Goals | 28-29 | 5-32 |

| Swimming Pool 1012 Concrete Pavers - Pool Deck 36-37 5-33 1017 Handicap Lift 30-31 5-33 1017 Handicap Lift 30-31 5-33 1005 Pool Filtration Refurbishment Allowance 31-32 5-34 1005 Pool Resurfacing/Tile 29-30 5-34 1010 Pool Starting Blocks 26-27 5-35 1020 Refurbishment Allowance - Slide Tower Frame 27-28 5-35 1020 Refurbishment Allowance - Slide Tower Frame 28-29 5-36 103 Slide Refurbishment Allowance 27-28 5-36 103 Slide Refurbishment Allowance 27-28 5-36 1089 Starting Blocks 26-27 5-37 Splash Pad | Asset I | DDescription | Replacement | Page | | |
|--|---|-------------------------------------|---|---|-------|------|
| 1012 Concrete Pavers - Pool Deck 36-37 5-33 1017 Handicap Lift 30-31 5-33 1094 Pool Filtration Refurbishment Allowance 31-32 5-34 1005 Pool Resurfacing/Tile 29-30 5-34 1010 Pool Starting Blocks 26-27 5-35 1020 Refurbishment Allowance - Slide Tower Frame 27-28 5-35 1007 Shade Structure Frame 28-29 5-36 1013 Slide Refurbishment Allowance 27-28 5-36 1013 Slide Refurbishment Allowance 27-28 5-36 1089 Starting Blocks 26-27 5-37 | Swimn | ning Pool | | | | |
| 1017 Handicap Lift 30-31 5-33 1094 Pool Filtration Refurbishment Allowance 31-32 5-34 1005 Pool Resurfacing/Tile 29-30 5-34 1010 Pool Starting Blocks 26-27 5-35 1020 Refurbishment Allowance - Slide Tower Frame 27-28 5-35 1007 Shade Structure Frame 28-29 5-36 1013 Slide Refurbishment Allowance 27-28 5-36 1013 Slide Refurbishment Allowance 27-28 5-36 1089 Starting Blocks 26-27 5-37 | | | 36-37 | 5-33 | | |
| 1094 Pool Filtration Refurbishment Allowance 31-32 5-34 1005 Pool Resurfacing/Tile 29-30 5-34 1010 Pool Starting Blocks 26-27 5-35 1020 Refurbishment Allowance - Slide Tower Frame 28-29 5-36 1037 Shade Structure Frame 28-29 5-36 1013 Slide Refurbishment Allowance 27-28 5-36 1014 Slide Refurbishment Allowance 27-28 5-36 1089 Starting Blocks 26-27 5-37 Splash Pad | | | | | | |
| 1005 | | <u> </u> | | | | |
| 1010 Pool Starting Blocks 26-27 5-35 1020 Refurbishment Allowance - Slide Tower Frame 27-28 5-35 1027 Shade Structure Frame 28-29 5-36 1013 Slide Refurbishment Allowance 27-28 5-36 1089 Starting Blocks 26-27 5-37 Splash Pad | | | | | | |
| 1020 Refurbishment Allowance - Slide Tower Frame 27-28 5-35 1007 Shade Structure Frame 28-29 5-36 1013 Slide Refurbishment Allowance 27-28 5-36 1089 Starting Blocks 26-27 5-37 Splash Pad | | <u> </u> | | | | |
| 1007 Shade Structure Frame 28-29 5-36 1013 Slide Refurbishment Allowance 27-28 5-36 1089 Starting Blocks 26-27 5-37 | | | 27-28 | | | |
| Splash Pad 1095 | 1007 | Shade Structure Frame | 28-29 | | | |
| Splash Pad 1095 | 1013 | Slide Refurbishment Allowance | 27-28 | 5-36 | | |
| 1095 Filtration Refurbishment Allowance 47-48 5-38 1092 Shade Structure Frame 42-43 5-38 1088 Splash Pad Play Equipment Allowance 27-28 5-39 1087 Splash Pad ReSurfacing 29-30 5-39 Operating Expense 1068 Flooring - Community Room 23-24 5-41 1063 Park Benches 23-24 5-41 1037 Picnic Tables 23-24 5-42 1098 Playground Mulch/Carpet 23-24 5-42 1011 Pool Pumps/Equip Partial Replace 23-24 5-43 1034 Pool/Patio Furniture Partial Replace 23-24 5-43 1061 Sand Volleyball Court/Nets 23-24 5-44 1054 Shade Structures - Tennis Courts 23-24 5-44 1065 Soccer Goals & Nets 23-24 5-45 Components Not Included 1101 Building Foundations/Frames 23-24 5-46 1100 Pool Shell 23-24 <td< td=""><td>1089</td><td>Starting Blocks</td><td>26-27</td><td>5-37</td></td<> | 1089 | Starting Blocks | 26-27 | 5-37 | | |
| 1095 Filtration Refurbishment Allowance 47-48 5-38 1092 Shade Structure Frame 42-43 5-38 1088 Splash Pad Play Equipment Allowance 27-28 5-39 1087 Splash Pad ReSurfacing 29-30 5-39 Operating Expense 1068 Flooring - Community Room 23-24 5-41 1063 Park Benches 23-24 5-41 1037 Picnic Tables 23-24 5-42 1098 Playground Mulch/Carpet 23-24 5-42 1011 Pool Pumps/Equip Partial Replace 23-24 5-43 1034 Pool/Patio Furniture Partial Replace 23-24 5-43 1061 Sand Volleyball Court/Nets 23-24 5-44 1054 Shade Structures - Tennis Courts 23-24 5-44 1065 Soccer Goals & Nets 23-24 5-45 Components Not Included 1101 Building Foundations/Frames 23-24 5-46 1100 Pool Shell 23-24 <td< td=""><td>Splash</td><td>Pad</td><td></td><td></td></td<> | Splash | Pad | | | | |
| 1088 Splash Pad Play Equipment Allowance 27-28 5-39 1087 Splash Pad ReSurfacing 29-30 5-39 Operating Expense 1068 Flooring - Community Room 23-24 5-41 1063 Park Benches 23-24 5-41 1037 Picnic Tables 23-24 5-42 1098 Playground Mulch/Carpet 23-24 5-42 1011 Pool Pumps/Equip Partial Replace 23-24 5-43 1034 Pool/Patio Furniture Partial Replace 23-24 5-43 1061 Sand Volleyball Court/Nets 23-24 5-43 1054 Shade Structures - Tennis Courts 23-24 5-44 1065 Soccer Goals & Nets 23-24 5-44 1096 Splash Pad - Pumps/Equip Partial Replacement 23-24 5-45 Components Not Included 1101 Building Foundations/Frames 23-24 5-46 1100 Pool Shell 23-24 5-46 1104 Stormwater Pond Bank Rebuilding 23 | - | | 47-48 | 5-38 | | |
| Operating Expense 1068 Flooring - Community Room 23-24 5-41 1063 Park Benches 23-24 5-41 1037 Picnic Tables 23-24 5-42 1098 Playground Mulch/Carpet 23-24 5-42 1011 Pool Pumps/Equip Partial Replace 23-24 5-43 1034 Pool/Patio Furniture Partial Replace 23-24 5-43 1061 Sand Volleyball Court/Nets 23-24 5-43 1054 Shade Structures - Tennis Courts 23-24 5-44 1065 Soccer Goals & Nets 23-24 5-44 1096 Splash Pad - Pumps/Equip Partial Replacement 23-24 5-45 Components Not Included 1101 Building Foundations/Frames 23-24 5-46 1100 Pool Shell 23-24 5-46 1104 Stormwater Pond Bank Rebuilding 23-24 5-46 1105 Stormwater Pond Structures/Pipe 23-24 5-47 1102 Utility Lines 23-24 | 1092 | Shade Structure Frame | 42-43 | 5-38 | | |
| Operating Expense 1068 Flooring - Community Room 23-24 5-41 1063 Park Benches 23-24 5-41 1037 Picnic Tables 23-24 5-42 1098 Playground Mulch/Carpet 23-24 5-42 1011 Pool Pumps/Equip Partial Replace 23-24 5-43 1034 Pool/Patio Furniture Partial Replace 23-24 5-43 1061 Sand Volleyball Court/Nets 23-24 5-44 1054 Shade Structures - Tennis Courts 23-24 5-44 1065 Soccer Goals & Nets 23-24 5-44 1096 Splash Pad - Pumps/Equip Partial Replacement 23-24 5-45 Components Not Included 1101 Building Foundations/Frames 23-24 5-46 1104 Stormwater Pond Bank Rebuilding 23-24 5-46 1103 Stormwater Pond Dredging 23-24 5-46 1105 Stormwater Pond Structures/Pipe 23-24 5-47 1102 Utility Lines 2 | 1088 | Splash Pad Play Equipment Allowance | 27-28 | 5-39 | | |
| 1068 Flooring - Community Room 23-24 5-41 1063 Park Benches 23-24 5-41 1037 Picnic Tables 23-24 5-42 1098 Playground Mulch/Carpet 23-24 5-42 1011 Pool Pumps/Equip Partial Replace 23-24 5-43 1034 Pool/Patio Furniture Partial Replace 23-24 5-43 1061 Sand Volleyball Court/Nets 23-24 5-44 1054 Shade Structures - Tennis Courts 23-24 5-44 1065 Soccer Goals & Nets 23-24 5-44 1096 Splash Pad - Pumps/Equip Partial Replacement 23-24 5-45 Components Not Included 1101 Building Foundations/Frames 23-24 5-46 1100 Pool Shell 23-24 5-46 1104 Stormwater Pond Bank Rebuilding 23-24 5-46 1103 Stormwater Pond Dredging 23-24 5-46 1105 Stormwater Pond Structures/Pipe 23-24 5-47 1102 Utility Lines 23-24 5-47 <td <="" colspan="2" td=""><td>1087</td><td>- · · · · · · · · · · · · · · · · · · ·</td><td>29-30</td><td>5-39</td></td> | <td>1087</td> <td>- · · · · · · · · · · · · · · · · · · ·</td> <td>29-30</td> <td>5-39</td> | | 1087 | - · · · · · · · · · · · · · · · · · · · | 29-30 | 5-39 |
| 1068 Flooring - Community Room 23-24 5-41 1063 Park Benches 23-24 5-41 1037 Picnic Tables 23-24 5-42 1098 Playground Mulch/Carpet 23-24 5-42 1011 Pool Pumps/Equip Partial Replace 23-24 5-43 1034 Pool/Patio Furniture Partial Replace 23-24 5-43 1061 Sand Volleyball Court/Nets 23-24 5-44 1054 Shade Structures - Tennis Courts 23-24 5-44 1065 Soccer Goals & Nets 23-24 5-44 1096 Splash Pad - Pumps/Equip Partial Replacement 23-24 5-45 Components Not Included 1101 Building Foundations/Frames 23-24 5-46 1100 Pool Shell 23-24 5-46 1104 Stormwater Pond Bank Rebuilding 23-24 5-46 1103 Stormwater Pond Dredging 23-24 5-46 1105 Stormwater Pond Structures/Pipe 23-24 5-47 Total Funded Assets 58 Total Unfunded Assets <td< td=""><td>Onorot</td><td>ting Evnonce</td><td></td><td></td></td<> | Onorot | ting Evnonce | | | | |
| 1063 Park Benches 23-24 5-41 1037 Picnic Tables 23-24 5-42 1098 Playground Mulch/Carpet 23-24 5-42 1011 Pool Pumps/Equip Partial Replace 23-24 5-43 1034 Pool/Patio Furniture Partial Replace 23-24 5-43 1061 Sand Volleyball Court/Nets 23-24 5-44 1054 Shade Structures - Tennis Courts 23-24 5-44 1065 Soccer Goals & Nets 23-24 5-44 1096 Splash Pad - Pumps/Equip Partial Replacement 23-24 5-45 Components Not Included 1101 Building Foundations/Frames 23-24 5-46 1100 Pool Shell 23-24 5-46 1104 Stormwater Pond Bank Rebuilding 23-24 5-46 1103 Stormwater Pond Dredging 23-24 5-46 1105 Stormwater Pond Structures/Pipe 23-24 5-47 Total Funded Assets Total Funded Assets 58 Total Unfunded Assets 16 | _ | e . | 23-24 | 5_41 | | |
| 1037 Picnic Tables 23-24 5-42 1098 Playground Mulch/Carpet 23-24 5-42 1011 Pool Pumps/Equip Partial Replace 23-24 5-43 1034 Pool/Patio Furniture Partial Replace 23-24 5-43 1061 Sand Volleyball Court/Nets 23-24 5-44 1054 Shade Structures - Tennis Courts 23-24 5-44 1065 Soccer Goals & Nets 23-24 5-44 1096 Splash Pad - Pumps/Equip Partial Replacement 23-24 5-45 Components Not Included 1101 Building Foundations/Frames 23-24 5-46 1100 Pool Shell 23-24 5-46 1104 Stormwater Pond Bank Rebuilding 23-24 5-46 1103 Stormwater Pond Dredging 23-24 5-46 1105 Stormwater Pond Structures/Pipe 23-24 5-47 1102 Utility Lines 23-24 5-47 Total Funded Assets 58 Total Unfunded Assets 16 | | · · | | | | |
| 1098 Playground Mulch/Carpet 23-24 5-42 1011 Pool Pumps/Equip Partial Replace 23-24 5-43 1034 Pool/Patio Furniture Partial Replace 23-24 5-43 1061 Sand Volleyball Court/Nets 23-24 5-44 1054 Shade Structures - Tennis Courts 23-24 5-44 1065 Soccer Goals & Nets 23-24 5-44 1096 Splash Pad - Pumps/Equip Partial Replacement 23-24 5-45 Components Not Included 1101 Building Foundations/Frames 23-24 5-46 1100 Pool Shell 23-24 5-46 1104 Stormwater Pond Bank Rebuilding 23-24 5-46 1103 Stormwater Pond Structures/Pipe 23-24 5-46 1105 Stormwater Pond Structures/Pipe 23-24 5-47 1102 Utility Lines 23-24 5-47 Total Funded Assets 58 Total Unfunded Assets 16 | | | | | | |
| 1011 Pool Pumps/Equip Partial Replace 23-24 5-43 1034 Pool/Patio Furniture Partial Replace 23-24 5-43 1061 Sand Volleyball Court/Nets 23-24 5-44 1054 Shade Structures - Tennis Courts 23-24 5-44 1065 Soccer Goals & Nets 23-24 5-44 1096 Splash Pad - Pumps/Equip Partial Replacement 23-24 5-45 Components Not Included 1101 Building Foundations/Frames 23-24 5-46 1100 Pool Shell 23-24 5-46 1104 Stormwater Pond Bank Rebuilding 23-24 5-46 1103 Stormwater Pond Dredging 23-24 5-46 1105 Stormwater Pond Structures/Pipe 23-24 5-47 1102 Utility Lines 23-24 5-47 Total Funded Assets 58 Total Unfunded Assets 16 | | | | | | |
| 1034 Pool/Patio Furniture Partial Replace 23-24 5-43 1061 Sand Volleyball Court/Nets 23-24 5-44 1054 Shade Structures - Tennis Courts 23-24 5-44 1065 Soccer Goals & Nets 23-24 5-44 1096 Splash Pad - Pumps/Equip Partial Replacement 23-24 5-45 Components Not Included 1101 Building Foundations/Frames 23-24 5-46 1100 Pool Shell 23-24 5-46 1104 Stormwater Pond Bank Rebuilding 23-24 5-46 1103 Stormwater Pond Dredging 23-24 5-46 1105 Stormwater Pond Structures/Pipe 23-24 5-47 1102 Utility Lines 23-24 5-47 Total Funded Assets Total Unfunded Assets 58 Total Unfunded Assets 16 | | •• | | | | |
| 1061 Sand Volleyball Court/Nets 23-24 5-44 1054 Shade Structures - Tennis Courts 23-24 5-44 1065 Soccer Goals & Nets 23-24 5-44 1096 Splash Pad - Pumps/Equip Partial Replacement 23-24 5-45 Components Not Included 1101 Building Foundations/Frames 23-24 5-46 1100 Pool Shell 23-24 5-46 1104 Stormwater Pond Bank Rebuilding 23-24 5-46 1103 Stormwater Pond Dredging 23-24 5-46 1105 Stormwater Pond Structures/Pipe 23-24 5-47 1102 Utility Lines 23-24 5-47 Total Funded Assets 58 Total Unfunded Assets 58 Total Unfunded Assets 16 | | | | | | |
| 1054 Shade Structures - Tennis Courts 23-24 5-44 1065 Soccer Goals & Nets 23-24 5-44 1096 Splash Pad - Pumps/Equip Partial Replacement 23-24 5-45 Components Not Included 1101 Building Foundations/Frames 23-24 5-46 1100 Pool Shell 23-24 5-46 1104 Stormwater Pond Bank Rebuilding 23-24 5-46 1103 Stormwater Pond Dredging 23-24 5-46 1105 Stormwater Pond Structures/Pipe 23-24 5-47 1102 Utility Lines 23-24 5-47 Total Funded Assets Total Unfunded Assets 58 Total Unfunded Assets 16 | | | | | | |
| 1065 Soccer Goals & Nets 23-24 5-44 1096 Splash Pad - Pumps/Equip Partial Replacement 23-24 5-45 Components Not Included 1101 Building Foundations/Frames 23-24 5-46 1100 Pool Shell 23-24 5-46 1104 Stormwater Pond Bank Rebuilding 23-24 5-46 1103 Stormwater Pond Dredging 23-24 5-46 1105 Stormwater Pond Structures/Pipe 23-24 5-47 1102 Utility Lines 23-24 5-47 Total Funded Assets Total Unfunded Assets 58 Total Unfunded Assets 16 | | <u>•</u> | | | | |
| 1096 Splash Pad - Pumps/Equip Partial Replacement 23-24 5-45 Components Not Included 1101 Building Foundations/Frames 23-24 5-46 1100 Pool Shell 23-24 5-46 1104 Stormwater Pond Bank Rebuilding 23-24 5-46 1103 Stormwater Pond Dredging 23-24 5-46 1105 Stormwater Pond Structures/Pipe 23-24 5-47 1102 Utility Lines 23-24 5-47 Total Funded Assets Total Unfunded Assets 58 Total Unfunded Assets 16 | | | | | | |
| Components Not Included 1101 Building Foundations/Frames 23-24 5-46 1100 Pool Shell 23-24 5-46 1104 Stormwater Pond Bank Rebuilding 23-24 5-46 1103 Stormwater Pond Dredging 23-24 5-46 1105 Stormwater Pond Structures/Pipe 23-24 5-47 1102 Utility Lines 23-24 5-47 Total Funded Assets 58 Total Unfunded Assets 16 | | | | | | |
| 1101 Building Foundations/Frames 23-24 5-46 1100 Pool Shell 23-24 5-46 1104 Stormwater Pond Bank Rebuilding 23-24 5-46 1103 Stormwater Pond Dredging 23-24 5-46 1105 Stormwater Pond Structures/Pipe 23-24 5-47 1102 Utility Lines 23-24 5-47 Total Funded Assets 58 Total Unfunded Assets 16 | | ~ | | | | |
| 1100 Pool Shell 23-24 5-46 1104 Stormwater Pond Bank Rebuilding 23-24 5-46 1103 Stormwater Pond Dredging 23-24 5-46 1105 Stormwater Pond Structures/Pipe 23-24 5-47 1102 Utility Lines 23-24 5-47 Total Funded Assets 58 Total Unfunded Assets 16 | - | | | | | |
| 1104 Stormwater Pond Bank Rebuilding 23-24 5-46 1103 Stormwater Pond Dredging 23-24 5-46 1105 Stormwater Pond Structures/Pipe 23-24 5-47 1102 Utility Lines 23-24 5-47 Total Funded Assets 58 Total Unfunded Assets 16 | | | | 5-46 | | |
| 1103 Stormwater Pond Dredging 23-24 5-46 1105 Stormwater Pond Structures/Pipe 23-24 5-47 1102 Utility Lines 23-24 5-47 Total Funded Assets 58 Total Unfunded Assets 16 | 1100 | Pool Shell | 23-24 | 5-46 | | |
| 1105 Stormwater Pond Structures/Pipe 23-24 5-47 1102 Utility Lines 23-24 5-47 Total Funded Assets 58 Total Unfunded Assets 16 | 1104 | Stormwater Pond Bank Rebuilding | 23-24 | 5-46 | | |
| Total Funded Assets Total Unfunded Assets 16 Total Funded Assets 16 | 1103 | Stormwater Pond Dredging | 23-24 | 5-46 | | |
| Total Funded Assets 58 Total Unfunded Assets 16 | | - | | | | |
| Total Unfunded Assets <u>16</u> | 1102 | Utility Lines | 23-24 | 5-47 | | |
| Total Unfunded Assets <u>16</u> | | Total Funded Assets | 58 | | | |
| <u> </u> | | Total Unfunded Assets | | | | |
| 7 1 | | Total Assets | $\overline{\phantom{0000000000000000000000000000000000$ | | | |

Monument Sign Refurbishment Allowance - 2026

| Asset ID | 1030 | 1 Lump Sum Asset Actual Cost Percent Replacement | @ \$12,000.00 \$12,000.00 100% |
|-------------------|----------------------|--|--------------------------------------|
| Category Mi | isc. Site Components | Future Cost | \$13,304.61 |
| Placed in Service | June 2015 | | |
| Useful Life | 12 | | |
| Replacement Year | 26-27 | | |
| Remaining Life | 3 | | |



Stre

| eet Signage Allowance - | 2031 | 14 Each | @ \$1,200.00 |
|--------------------------------|----------|---------------------|--------------|
| Asset ID | 1027 | Asset Actual Cost | \$16,800.00 |
| | | Percent Replacement | 100% |
| Category Misc. Site Components | | Future Cost | \$22,122.39 |
| Placed in Service | May 2002 | | |
| Useful Life | 25 | | |
| Adjustment | 5 | | |
| Replacement Year | 31-32 | | |
| Remaining Life | 8 | | |
| | | | |

Wood Bridge Refurbishment Allowance - 2029

| Asset ID | 1028 | 1 Lump Sum Asset Actual Cost Percent Replacement | @ \$24,000.00 \$24,000.00 100% |
|--------------------------------|----------|--|--------------------------------------|
| Category Misc. Site Components | | Future Cost | \$29,502.13 |
| Placed in Service | May 2002 | | |
| Useful Life | 25 | | |
| Adjustment | 3 | | |
| Replacement Year | 29-30 | | |
| Remaining Life | 6 | | |

| Retention Pond Repair Allowance - 2026 | | 1 Each | @ \$30,000.00 |
|--|-------------------|---------------------|---------------|
| Asset ID | 1085 | Asset Actual Cost | \$30,000.00 |
| | | Percent Replacement | 100% |
| Category | Stormwater System | Future Cost | \$33,261.54 |
| Placed in Service | May 2002 | | |
| Useful Life | 20 | | |
| Adjustment | 5 | | |
| Replacement Year | 26-27 | | |
| Remaining Life | 3 | | |

Included in this allowance is general repair of structures and necessary cleaning not included in the operational budget.

Street Drainage System Allowance - 2026

| | | I Lump Sum | @ \$30,000.00 |
|-------------------|-------------------|---------------------|---------------|
| Asset ID | 1084 | Asset Actual Cost | \$30,000.00 |
| | | Percent Replacement | 100% |
| Category | Stormwater System | Future Cost | \$33,261.54 |
| Placed in Service | May 2002 | | |
| Useful Life | 20 | | |
| Adjustment | 5 | | |
| Replacement Year | 26-27 | | |
| Remaining Life | 3 | | |
| | | | |

The majority of the storm water drainage system is composed of concrete pipe with a useful life that exceeds this report. We have included an allowance for repairs that my occur such as seperation of pipe and structure due to erosion of the surrounding soil.

| Asphalt Mill/Overlay - | 2040 | 108,943 Square Yards | @ \$12.80 |
|------------------------|--------------------|----------------------|----------------|
| Asset ID | 1075 | Asset Actual Cost | \$1,394,470.40 |
| | | Percent Replacement | 100% |
| Category | Street Resurfacing | Future Cost | \$2,502,621.93 |
| Placed in Service | October 2020 | | |
| Useful Life | 20 | | |
| Replacement Year | 40-41 | | |
| Remaining Life | 17 | | |

Concrete Curb & Gutter Allowance - 2025

| | | 1 Lump Sum | @ \$8,000.00 |
|-------------------|---------------|---------------------|--------------|
| Asset ID | 1083 | Asset Actual Cost | \$8,000.00 |
| | | Percent Replacement | 100% |
| Category | Site Concrete | Future Cost | \$8,569.80 |
| Placed in Service | May 2023 | | |
| Useful Life | 3 | | |
| Replacement Year | 25-26 | | |
| Remaining Life | 2 | | |
| | | | |

CDD has 82,778 LFT of concrete gutter supporting street drainage. Some will be replace at the time of street resurfacing.

Concrete Sidewalk Allowance - 2025

| | | 1 Lump Sum | @ \$8,000.00 |
|-------------------|---------------|---------------------|--------------|
| Asset ID | 1082 | Asset Actual Cost | \$8,000.00 |
| | | Percent Replacement | 100% |
| Category | Site Concrete | Future Cost | \$8,569.80 |
| Placed in Service | May 2023 | | |
| Useful Life | 3 | | |
| Replacement Year | 25-26 | | |
| Remaining Life | 2 | | |
| | | | |

Asphalt Resurfacing 40% - Parking Lot - 2026

| Asset ID | 1022 | 5,153 Square Yards Asset Actual Cost Percent Replacement | @ \$16.20 \$83,478.60 100% |
|---------------------------------|----------|--|----------------------------------|
| CategoryParking Lot Resurfacing | | Future Cost | \$92,554.22 |
| Placed in Service | May 2002 | | |
| Useful Life | 25 | | |
| Replacement Year | 26-27 | | |
| Remaining Life | 3 | | |



Includes milling and 1-1/2" overlay. CDD has 40% cost share with Golf Club. The amount included is 100%.

| @ \$4,000.00 | 18 Each | - 2027 | Intersection Light Poles |
|-----------------------------------|--|---------------------------|--|
| \$72,000.00 | Asset Actual Cost | 1029 | Asset ID |
| 100% | Percent Replacement | | |
| \$82,621.66 | Future Cost | Site Lighting | Category |
| | | May 2002 | Placed in Service |
| | | 26 | Useful Life |
| | | 27-28 | Replacement Year |
| | | 4 | Remaining Life |
| @ \$1 400 00 | 10 Each | Lot - 2025 | Light Bollards - Parking |
| @ \$1,400.00 \$5,600.00 | 10 Each Asset Actual Cost | | |
| @ \$1,400.00 \$5,600.00 40% | Asset Actual Cost | 2 Lot - 2025 1023 | Light Bollards - Parking Asset ID |
| \$5,600.00 | | 1023 | |
| \$5,600.00 40% | Asset Actual Cost Percent Replacement | | Asset ID |
| \$5,600.00 40% | Asset Actual Cost Percent Replacement | 1023 Site Lighting | Asset ID Category |
| \$5,600.00 40% | Asset Actual Cost Percent Replacement | Site Lighting May 2002 | Asset ID Category Placed in Service |
| \$5,600.00 40% | Asset Actual Cost Percent Replacement | Site Lighting May 2002 22 | Asset ID Category Placed in Service Useful Life |

Light Bollards - Tennis Court Walk - 2046

| Asset ID | 1051 | 8 Each Asset Actual Cost Percent Replacement | @ \$1,200.00 \$9,600.00 100% |
|-------------------|---------------|--|------------------------------------|
| Category | Site Lighting | Future Cost | \$21,178.70 |
| Placed in Service | December 2021 | | |
| Useful Life | 25 | | |
| Replacement Year | 46-47 | | |
| Remaining Life | 23 | | |

Light Bollards - Tennis Court Walk continued...



| Light Poles - Parking Lo | ot - 2025 | 20 Each | @ \$3,000.00 |
|--------------------------|---------------|---------------------|--------------|
| Asset ID | 1024 | Asset Actual Cost | \$24,000.00 |
| | | Percent Replacement | 40% |
| Category | Site Lighting | Future Cost | \$25,709.40 |
| Placed in Service | May 2002 | | |
| Useful Life | 22 | | |
| Adjustment | 2 | | |
| Replacement Year | 25-26 | | |
| Remaining Life | 2 | | |
| | | | |

CDD has 40% cost share with Golf Club.

| Light Poles - Pool - 2026 | | 7 Each | @ \$3,800.00 |
|---------------------------|---------------|---------------------|--------------|
| Asset ID | 1008 | Asset Actual Cost | \$26,600.00 |
| | | Percent Replacement | 100% |
| Category | Site Lighting | Future Cost | \$29,491.90 |
| Placed in Service | May 2002 | | |
| Useful Life | 25 | | |
| Replacement Year | 26-27 | | |
| Remaining Life | 3 | | |

Light Poles - Pool continued...



Light Poles - Tennis Courts - 2026

 - Tennis Courts - 2026
 18 Each
 @ \$3,400.00

 Asset ID
 1055
 Asset Actual Cost
 \$61,200.00

 Percent Replacement
 100%

 Category
 Site Lighting
 Future Cost
 \$67,853.53

Category Site Lighting
Placed in Service May 2002
Useful Life 25
Replacement Year 26-27
Remaining Life 3



Access Control Allowance - 2025

@ \$5,000.00 Asset ID 1041 Asset Actual Cost \$5,000.00 Percent Replacement 100% \$5,356.12 CaFegraing/Gates/Access Control **Future Cost**

1 Each

Placed in Service May 2002 Useful Life 20 Adjustment 4 Replacement Year 25-26 Remaining Life 2

Aluminum Fence - Basketball Court - 2031

134 Linear Feet @ \$42.00 Asset ID 1090 Asset Actual Cost \$5,628.00 Percent Replacement 100% CaFegraing/Gates/Access Control **Future Cost** \$7,411.00

Placed in Service May 2002 Useful Life 30 Replacement Year 31-32 Remaining Life 8



Aluminum Fencing - Pool - 2026

Asset ID 1009 Asset Actual Cost \$37,086.00 Percent Replacement 100% **Future Cost** \$41,117.91

883 LFT

@ \$42.00

CaFegoring/Gates/Access Control Placed in Service May 2002 Useful Life 25 Replacement Year 26-27 Remaining Life 3

> Community Advisors Page 5-16 April 15, 2023

Aluminum Fencing - Pool continued...



Fencing inventory includes aluminum fence located at perimeter of pool wading pool, slide structure and pool equipment area.

Chain Link Fence - Tennis Courts - 2031

| | | 1,040 Linear Feet | @ \$31.00 |
|---------------------------------|----------|---------------------|-------------|
| Asset ID | 1052 | Asset Actual Cost | \$32,240.00 |
| | | Percent Replacement | 100% |
| CaFegroing/Gates/Access Control | | Future Cost | \$42,453.92 |
| Placed in Service | May 2002 | | |
| Useful Life | 30 | | |
| Replacement Year | 31-32 | | |
| Remaining Life | 8 | | |



Irrigation Pumps/Equip. Partial Allowance - 2023

| | | 1 Lump Sum | @ \$8,000.00 |
|----------------------------------|----------|---------------------|--------------|
| Asset ID | 1025 | Asset Actual Cost | \$8,000.00 |
| | | Percent Replacement | 100% |
| Categorlyandscaping & Irrigation | | Future Cost | \$8,000.00 |
| Placed in Service | May 2002 | | |
| Useful Life | 15 | | |
| Replacement Year | 23-24 | | |
| Remaining Life | 0 | | |
| | | | |

Irrigation of common landscape and turf areas is provided by local utility and in some areas, water supplied by the golf club pump house. The pumps and equipment for the golf club pump system was installed in 2001 and has a useful life of 10-15 years. The cost sharing agreement between the CDD indicates the CDD is responsible for 10% of this cost but total cost is unknow. We have applied an allowance.

Landscaping Replacement Allowance - 2023

| Asset ID | 1026 | 1 Lump Sum Asset Actual Cost Percent Replacement | @ \$8,000.00 \$8,000.00 100% |
|----------------------------------|-----------|--|------------------------------------|
| Categorlyandscaping & Irrigation | | Future Cost | \$8,000.00 |
| Placed in Service | June 2018 | | |
| Useful Life | 1 | | |
| Replacement Year | 23-24 | | |
| Remaining Life | 0 | | |

Exterior Door Allowance - 2037

Asset ID 1001

Category Building Components
Placed in Service
Useful Life
Cottober 2012
Useful Life
Replacement Year
Remaining Life
Useful Life
14



Refurbishment Allowance - Pool Restrooms - 2027

1 Lump Sum @ \$60,000.00
Asset ID 1086 Asset Actual Cost \$60,000.00
Percent Replacement 100%
Category Building Components Future Cost \$68,851.38

Category Placed in Service Useful Life Adjustment Adjustment Replacement Year Remaining Life Building Components May 2002

May 2002

6

20

27-28



Community Advisors Page 5-19 April 15, 2023

Vinyl Flooring - Aerobics Room - 2032

| | | 600 Square Feet | @ \$8.60 |
|-------------------|------------|---------------------|------------|
| Asset ID | 1070 | Asset Actual Cost | \$5,160.00 |
| | | Percent Replacement | 100% |
| Category Building | Components | Future Cost | \$7,032.55 |

Placed in Service
Useful Life
Replacement Year
Remaining Life
October 2012
20
32-33
Remaining Life



Wood Cabinets & Stone Top - Community Room - 2034

| | | 8 Linear Feet | @ \$400.00 |
|-------------------|----------------------------|---------------------|------------|
| Asset ID | 1071 | Asset Actual Cost | \$3,200.00 |
| | | Percent Replacement | 100% |
| Category | Building Components | Future Cost | \$4,671.90 |
| Placed in Service | October 2012 | | |
| Useful Life | 20 | | |
| Adjustment | 2 | | |
| Replacement Year | 34-35 | | |
| Remaining Life | 11 | | |
| | | | |

Wood Cabinets & Stone Top - Community Room continued...



Asphalt Shingles - Fitness Center - 2032

| Asset ID | 1033 | 30 Squares Asset Actual Cost Percent Replacement | @ \$460.00 \$13,800.00 100% |
|-------------------|--------------|--|-----------------------------------|
| Category | Roofing | Future Cost | \$18,807.98 |
| Placed in Service | October 2012 | | |
| Useful Life | 20 | | |
| Replacement Year | 32-33 | | |
| Remaining Life | 9 | | |



Asphalt Shingles - Original Buildings - 2025

| | | 68 Squares | @ \$460.00 |
|-------------------|----------|---------------------|-------------|
| Asset ID | 1031 | Asset Actual Cost | \$31,280.00 |
| | | Percent Replacement | 100% |
| Category | Roofing | Future Cost | \$33,507.92 |
| Placed in Service | May 2002 | | |
| Useful Life | 20 | | |
| Adjustment | 4 | | |
| Replacement Year | 25-26 | | |
| Remaining Life | 2 | | |

Asphalt Shingles - Original Buildings continued...



Asphalt Shingles - Slide Tower - 2041

Asset ID 1032

Category Roofing
Placed in Service May 2022
Useful Life 20
Replacement Year 41-42
Remaining Life 18

9 Squares @ \$700.00
Asset Actual Cost \$6,300.00
Percent Replacement 100%
Future Cost \$11,702.18



| Audio System - 2027 | | 1.1. 0 | © ¢4,000,00 |
|---------------------------|---------------------|---------------------------------|----------------------------|
| Asset ID | 1091 | 1 Lump Sum Asset Actual Cost | @ \$4,000.00 \$4,000.00 |
| Asset ID | 1071 | Percent Replacement | 100% |
| Gatenious e Fixtu | res & Equipment | Future Cost | \$4,590.09 |
| Placed in Service | May 2020 | | . , |
| Useful Life | 8 | | |
| Replacement Year | 27-28 | | |
| Remaining Life | 4 | | |
| Camera System Allowand | ces - 2029 | 1 Lump Sum | @ \$12,000.00 |
| Asset ID | 1040 | Asset Actual Cost | \$12,000.00 |
| 115500 12 | 1010 | Percent Replacement | 100% |
| Gateniouv e Fixtu | res & Equipment | Future Cost | \$14,751.06 |
| Placed in Service | May 2022 | | , - ·,· · · · · · |
| Useful Life | 8 | | |
| Replacement Year | 29-30 | | |
| Remaining Life | 6 | | |
| Fitness Equipment Annua | al Allowance - 2024 | | |
| | | 1 Lump Sum | @ \$4,000.00 |
| Asset ID | 1035 | Asset Actual Cost | \$4,000.00 |
| | | Percent Replacement | 100% |
| Gategiouy e Fixtu | res & Equipment | Future Cost | \$4,140.00 |
| Placed in Service | October 2023 | | |
| Useful Life | 1 | | |
| Adjustment | 1 | | |
| Replacement Year | 24-25 | | |
| Remaining Life | 1 | | |
| Pool/Patio Furniture Full | Replace Allowance | e - 2039 | |
| | | 1 Lump Sum | @ \$50,000.00 |
| Asset ID | 1093 | Asset Actual Cost | \$50,000.00 |
| | | Percent Replacement | 100% |
| | res & Equipment | Future Cost | \$86,699.30 |
| Placed in Service | May 2015 | | |
| Useful Life | 25 | | |
| Replacement Year | 39-40 | | |
| Remaining Life | 16 | | |

Pool/Patio Furniture Full Replace Allowance continued...



Amenity Exterior - 2023

Asset ID 1046 Asset Actual Cost \$11,106.00
Percent Replacement 100%
Category Painting Future Cost \$11,106.00

Category Painting
Placed in Service October 2012
Useful Life 8
Replacement Year 23-24
Remaining Life 0



Slide Tower Support Structure - 2030

Asset ID 1047 Asset Actual Cost \$1,856.00
Percent Replacement 100%
Category Painting Future Cost \$2,361.35

Placed in Service March 2023
Useful Life 8
Replacement Year 30-31
Remaining Life 7



Community Advisors Page 5-26 April 15, 2023

| Heat Pump 1 - 2025 Asset ID Category Placed in Service Useful Life Replacement Year Remaining Life | Mechanical Systems December 2013 12 25-26 2 | 5 Tons Asset Actual Cost Percent Replacement Future Cost | @ \$1,600.00 \$8,000.00 100% \$8,569.80 |
|--|---|---|--|
| Heat Pump 2 - 2024 | | 5 Tons | @ \$1,600.00 |
| Asset ID | 1050 | Asset Actual Cost | \$8,000.00 |
| | | Percent Replacement | 100% |
| Category | Mechanical Systems | Future Cost | \$8,280.00 |
| Placed in Service | October 2012 | | |
| Useful Life | 12 | | |
| Replacement Year | 24-25 | | |
| Remaining Life | 1 | | |
| Heat Pump 3 - 2024 | | 7 Tons | @ \$1,600.00 |
| Asset ID | 1049 | Asset Actual Cost | \$11,200.00 |
| | | Percent Replacement | 100% |
| Category | Mechanical Systems | Future Cost | \$11,592.00 |
| Placed in Service | October 2012 | | |
| Useful Life | 12 | | |
| Replacement Year | 24-25 | | |
| Remaining Life | 1 | | |

Asphalt Court Resurfacing (Color Coat) - 2025

| Asset ID | 1053 | 3,200 Square Yards Asset Actual Cost Percent Replacement | @ \$8.90 \$28,480.00 100% |
|-------------------|---------------|--|---------------------------------|
| Category | Tennis Courts | Future Cost | \$30,508.49 |
| Placed in Service | July 2018 | | |
| Useful Life | 8 | | |
| Replacement Year | 25-26 | | |
| Remaining Life | 2 | | |



Tennis Court Replacement - 2041

| | | 3,200 Square Yards | @ \$32.00 |
|-------------------|---------------|---------------------|--------------|
| Asset ID | 1097 | Asset Actual Cost | \$102,400.00 |
| | | Percent Replacement | 100% |
| Category | Tennis Courts | Future Cost | \$190,206.89 |
| Placed in Service | July 2002 | | |
| Useful Life | 40 | | |
| Replacement Year | 41-42 | | |
| Remaining Life | 18 | | |
| | | | |



Community Advisors Page 5-28 April 15, 2023

Play Equipment Allowance - 2026

 ment Allowance - 2026
 1 Lump Sum
 @ \$40,000.00

 Asset ID
 1062
 Asset Actual Cost
 \$40,000.00

 Percent Replacement
 100%

 Category
 Playground
 Future Cost
 \$44,348.71

Placed in Service May 2012
Useful Life 15
Replacement Year 26-27
Remaining Life 3



Shade Structure Frame - 2036

Asset ID 1059 Asset Actual Cost \$6,280.00

Percent Replacement 100%

Category Playground Future Cost \$9,821.64

Placed in Service August 2012
Useful Life 25
Replacement Year 36-37
Remaining Life 13



Wood Playground Equipment Refurbishment - 2023

| | | 1 Lump Sum | @ \$6,000.00 |
|-------------------|------------|---------------------|--------------|
| Asset ID | 1064 | Asset Actual Cost | \$6,000.00 |
| | | Percent Replacement | 100% |
| Category | Playground | Future Cost | \$6,000.00 |
| Placed in Service | May 2015 | | |
| Useful Life | 3 | | |
| Replacement Year | 23-24 | | |
| Remaining Life | 0 | | |



The District has elected to refurbish and not replace the wood play equipment and fencing over time. We have included an allowance for this refurbishment.

Asphalt Resurfacing (Color Coat) - 2024

| Asset ID | 1057 | 1,078 Square Yards Asset Actual Cost Percent Replacement | @ \$5.80 \$6,252.40 100% |
|-------------------|--------------------------|--|--------------------------------|
| Category | Basketball Courts | Future Cost | \$6,471.23 |
| Placed in Service | June 2020 | | |
| Useful Life | 5 | | |
| Replacement Year | 24-25 | | |
| Remaining Life | 1 | | |



Courts require crack filling at this time.

Basketball Court Replacement - 2036

| | | 1,078 Square Yards | @ \$32.00 |
|-------------------|--------------------------|---------------------|-------------|
| Asset ID | 1099 | Asset Actual Cost | \$34,496.00 |
| | | Percent Replacement | 100% |
| Category | Basketball Courts | Future Cost | \$53,950.23 |
| Placed in Service | June 2002 | | |
| Useful Life | 35 | | |
| Replacement Year | 36-37 | | |
| Remaining Life | 13 | | |
| | | | |

Basketball Court Replacement continued...



Courts require crack filling at this time.

| Basketba | ll Poles | & Goal | ls - 2028 |
|----------|----------|--------|-----------|
|----------|----------|--------|-----------|

| asketball Poles & G | oals - 2028 | 4 Each | @ \$3,000.00 |
|---------------------|--------------------------|---------------------|--------------|
| Asset ID | 1058 | Asset Actual Cost | \$12,000.00 |
| | | Percent Replacement | 100% |
| Category | Basketball Courts | Future Cost | \$14,252.24 |
| Placed in Service | June 2012 | | |
| Useful Life | 15 | | |
| Adjustment | 2 | | |
| Replacement Year | 28-29 | | |
| Remaining Life | 5 | | |



Concrete Pavers - Pool Deck - 2036

Asset ID 1012 Asset Actual Cost \$107,760.00
Percent Replacement 100%
Category Swimming Pool Future Cost \$168,531.90

Placed in Service May 2002
Useful Life 35
Replacement Year 36-37
Remaining Life 13



Handicap Lift - 2030

Asset ID 1017 Asset Actual Cost \$3,400.00

Percent Replacement 100%

Category Swimming Pool
Placed in Service May 2011
Useful Life 20
Replacement Year 30-31
Remaining Life 7



Community Advisors Page 5-33 April 15, 2023

Pool Filtration Refurbishment Allowance - 2031


| Asset ID | 1094 | 1 Lump Sum Asset Actual Cost Percent Replacement | @ \$30,000.00 \$30,000.00 100% |
|-------------------|----------------------|--|--------------------------------------|
| Category | Swimming Pool | Future Cost | \$39,504.27 |
| Placed in Service | May 2002 | | |
| Useful Life | 30 | | |
| Replacement Year | 31-32 | | |
| Remaining Life | 8 | | |



Pool Resurfacing/Tile - 2029

Asset ID 1005 Asset Actual Cost \$2

Category Swimming Pool
Placed in Service June 2018
Useful Life 12
Replacement Year 29-30
Remaining Life 6





Pool Starting Blocks - 2026

| ol Starting Blocks | - 2026 | 6 Each | @ \$2,000.00 |
|--------------------|---------------|---------------------|--------------|
| Asset ID | 1010 | Asset Actual Cost | \$12,000.00 |
| | | Percent Replacement | 100% |
| Category | Swimming Pool | Future Cost | \$13,304.61 |
| Placed in Service | May 2002 | | |
| Useful Life | 15 | | |
| Adjustment | 10 | | |
| Replacement Year | 26-27 | | |
| Remaining Life | 3 | | |
| | | | |



Refurbishment Allowance - Slide Tower Frame - 2027

| Asset ID | 1020 | 1 Each Asset Actual Cost Percent Replacement | @ \$3,000.00 \$3,000.00 100% |
|-------------------|---------------|--|------------------------------------|
| Category | Swimming Pool | Future Cost | \$3,442.57 |
| Placed in Service | December 2022 | | |
| Useful Life | 5 | | |
| Replacement Year | 27-28 | | |
| Remaining Life | 4 | | |



Includes cleaning, welding and painting as necessary.

Community Advisors Page 5-35 April 15, 2023

Shade Structure Frame - 2028

| ade Structure Frame | e - 2028 | 2 Each | @ \$6,000.00 |
|---------------------|----------------------|---------------------|--------------|
| Asset ID | 1007 | Asset Actual Cost | \$12,000.00 |
| | | Percent Replacement | 100% |
| Category | Swimming Pool | Future Cost | \$14,252.24 |
| Placed in Service | May 2002 | | |
| Useful Life | 25 | | |
| Adjustment | 2 | | |
| Replacement Year | 28-29 | | |
| Remaining Life | 5 | | |



700 Sf @ \$6.00/SF

Slide Refurbishment Allowance - 2027

| | | 1 Lump Sum | @ \$20,000.00 |
|-------------------|---------------|---------------------|---------------|
| Asset ID | 1013 | Asset Actual Cost | \$20,000.00 |
| | | Percent Replacement | 100% |
| Category | Swimming Pool | Future Cost | \$22,950.46 |
| Placed in Service | May 2020 | | |
| Useful Life | 8 | | |
| Replacement Year | 27-28 | | |
| Remaining Life | 4 | | |
| | | | |

Slide Refurbishment Allowance continued...



Starting Blocks - 2026

Asset ID 1089

Category Swimming Pool
Placed in Service May 2002
Useful Life 25
Replacement Year 26-27
Remaining Life 3



Filtration Refurbishment Allowance - 2047

| Asset ID | 1095 | 1 Lump Sum Asset Actual Cost | @ \$8,000.00 \$8,000.00 |
|-------------------|------------|---------------------------------|----------------------------|
| | | Percent Replacement | 100% |
| Category | Splash Pad | Future Cost | \$18,266.63 |
| Placed in Service | July 2018 | | |
| Useful Life | 30 | | |
| Replacement Year | 47-48 | | |
| Remaining Life | 24 | | |



Shade Structure Frame - 2042

| ade Structure Frame | - 2042 | 2 Each | @ \$6,000.00 |
|---------------------|------------|---------------------|--------------|
| Asset ID | 1092 | Asset Actual Cost | \$12,000.00 |
| | | Percent Replacement | 100% |
| Category | Splash Pad | Future Cost | \$23,070.01 |
| Placed in Service | May 2018 | | |
| Useful Life | 25 | | |
| Replacement Year | 42-43 | | |
| Remaining Life | 19 | | |
| | | | |



700 Sf @ \$6.00/SF

Splash Pad Play Equipment Allowance - 2027

| Asset ID | 1088 | 1 Lump Sum Asset Actual Cost Percent Replacement | @ \$5,000.00 \$5,000.00 100% |
|-------------------|------------|--|------------------------------------|
| Category | Splash Pad | Future Cost | \$5,737.61 |
| Placed in Service | July 2018 | | |
| Useful Life | 10 | | |
| Replacement Year | 27-28 | | |
| Remaining Life | 4 | | |



1

| Splach | Pad | ReSurfaci | ing - 2029 |
|---------|-----|-----------|------------|
| Spiasii | rau | Nesultac. | mg - 2029 |

| lash Pad ReSurfacing - 2029 | | 1,800 Square Feet | @ \$22.00 |
|-----------------------------|------------|---------------------|-------------|
| Asset ID | 1087 | Asset Actual Cost | \$39,600.00 |
| | | Percent Replacement | 100% |
| Category | Splash Pad | Future Cost | \$48,678.51 |
| Placed in Service | July 2018 | | |
| Useful Life | 12 | | |
| Replacement Year | 29-30 | | |
| Remaining Life | 6 | | |
| | | | |

Splash Pad ReSurfacing continued...



Flooring - Community Room

Asset ID 1068

Asset Actual Cost Percent Replacement Future Cost

100%

Category Placed in Service No Useful Life Operating Expense May 2020



138 SY

Park Benches

Asset ID

Asset Actual Cost Percent Replacement Future Cost

100%

Category Placed in Service No Useful Life Operating Expense May 2002

1063



Community Advisors Page 5-41 April 15, 2023

Picnic Tables

Asset ID

1037

Asset Actual Cost Percent Replacement

Future Cost

100%

Category Placed in Service No Useful Life Operating Expense

August 2012





Playground Mulch/Carpet

Asset ID

1098

Asset Actual Cost Percent Replacement **Future Cost**

100%

Category Placed in Service No Useful Life Operating Expense May 2002





Pool Pumps/Equip Partial Replace

Asset ID 1011

Asset Actual Cost Percent Replacement Future Cost

100%

Category Placed in Service No Useful Life Operating Expense May 2018



Pool/Patio Furniture Partial Replace

Asset ID 1034

Asset Actual Cost Percent Replacement Future Cost

100%

Category Placed in Service No Useful Life Operating Expense May 2010



Sand Volleyball Court/Nets

No Useful Life

Asset ID 1061 Asset Actual Cost

Category Operating Expense Future Cost
Placed in Service May 2002

Shade Structures - Tennis Courts

Asset ID 1054 Asset Actual Cost
Percent Replacement 100%

Category Operating Expense Future Cost
Placed in Service May 2008
No Useful Life

Soccer Goals & Nets

Asset ID 1065 Asset Actual Cost

Percent Replacement 100%
Category Operating Expense Future Cost

Placed in Service May 2002

No Useful Life

Splash Pad - Pumps/Equip Partial Replacement

Asset ID 1096 Asset Actual Cost Percent Replacement

100% Category Operating Expense Future Cost July 2018

Placed in Service No Useful Life



| Building F | oundations | /Frames |
|-------------------|------------|---------|
|-------------------|------------|---------|

Asset ID 1101 Asset Actual Cost Percent Replacement

Categorymponents Not Included Placed in Service May 2002

No Useful Life

Pool Shell

Asset ID 1100 Asset Actual Cost

> Percent Replacement 100% **Future Cost**

Categorymponents Not Included Placed in Service May 2002

No Useful Life

Stormwater Pond Bank Rebuilding

Asset ID 1104 Asset Actual Cost

Categorymponents Not Included Placed in Service May 2002

No Useful Life

Percent Replacement

Future Cost

100%

100%

Future Cost

Stormwater Pond Dredging

Asset ID 1103 **Asset Actual Cost**

Percent Replacement 100% Categorymponents Not Included **Future Cost**

Placed in Service May 2002

No Useful Life

Stormwater Pond Structures/Pipe

Asset ID 1105 Asset Actual Cost

Percent Replacement
Categorymponents Not Included
Future Cost
Placed in Service
May 2002

No Useful Life

Utility Lines

Asset ID 1102 Asset Actual Cost

100%

Percent Replacement 100%
Categorymponents Not Included Future Cost

Placed in Service May 2002

No Useful Life

Report Navigation

- Executive Summary provides information about projected year end reserve balance, current annual contribution, interest, and inflation rates:
 - Level of Service is the type of reserve study
 - Funding Method is either Component Funding or Pooled Cash
 - Component Funding Contribution is a year one only amount
 - Current Funding Plan currently used by the Association
 - Recommended Funding Plan maintains adequate funding
- **Funding Model Projections** include both your current plan and our recommended plan. The information included in each column is described below:
 - Year begins with your study year generally for a 30-year term
 - Current cost is the current replacement of all components
 - Annual contribution is the amount placed in reserves each year
 - Annual interest earned on your funds
 - Annual expenditures are the projected component replacement cost by year
 - Projected ending balance is the year end reserve fund balance
 - Fully funded reserves are the fully funded balance for that year. Fully Funded formula is Fully Funded Balance= Component cost x Age/Useful Life
 - Percent Funded is a measure of fund strength
- Current Funding Projection is your current funding plan and how it performs
- Recommended Funding Model Projection is the plan we recommend
- Cash Flow is a 30-year statement that provides both income and expense information to quickly find when expenditures occur and the resulting financial status of your reserves
- **Annual Expenditure Detail** provides a year to year list of your projected expenditures This is a good section to review each year when preparing your budgets
- Condition Assessment (if included) is a brief description of major component condition
- **Component Inventory** contains a list of your components, remaining useful life and quantities we determined from our site visit and other means of measurement
- Component Detail Index allows quick access to the detail we have included for each component separated into categories
- Component Detail provides a listing of each component, quantities or allowances and photographs of major ones
- Methodology Terms of Service Company Profile are our Disclosure sections with information about our assumptions, methods of work and our credentials

METHODOLOGY

Reserve Analysis is a process that identifies capital expenses the District can expect and creates a plan to fund them. This is accomplished by a site visit to visually evaluate components to measure quantities and determine their remaining life. Component Selection Process is based on the Community Associations Institute (CAI) standards for reserve studies and selection of components.

Component must be a commonly owned, have a limited and predictable life, replacement cost must be above a minimum threshold cost. Useful life and replacement cost are obtained from site inspection by experienced inspectors and our database of information, historical information, local Vendors and comparison of similar component cost found at other properties.

The funding plan we develop includes; adequate cash balances, even contributions so all owners pay their fair share over time and moderate contributions with acceptable increases. Percent Funded is defined by industry standards as 70-100% strong, 30-70% fair or adequate and below 30% weak or inadequate. <u>Baseline Funding</u> maintains funds above zero resulting is a high risk of special assessments or deferred maintenance and should be avoided. Threshold Funding maintains reserves above a "Threshold" level providing adequate funding with moderate risk; using this method requires regular analysis updates.

CREDENTIALS

Community Advisors, LLC provides capital reserve planning, property inspection, and construction oversight for a broad base of clients including High-rise Condominiums, Homeowner Associations, Churches, Private Schools, Time Shares, Active Adult, Municipal Utility Plants, Marinas, Historic Buildings & Museums and commercial investment properties.

Personal Service attention to detail, quick response and valued client relationships.

Range of Experience includes a broad selection of building types, ages and uses from protected historic structures to new communities ready for developer turnover. As commercial general contractors we have experience building many of the types of structure we now provide reserve analysis for, so we understand potential problem areas. As commercial inspectors we have experienced a variety of structural and cosmetic conditions offering solutions for repair. Areas of expertise include MEP systems, energy management, life safety systems, building envelope and roof components, marine structures, street and other site improvements.

Detailed Site Evaluation is Conducted to make sure we know your property and include all your assets in our analysis. With our years of experience with community development and commercial construction projects we understand both horizontal and vertical construction and utilize realistic replacement cost and useful life projections in our analysis. Financial Plan Meets CAI & APRA Standards with information obtained during the site visit we build a custom-made financial plan to ensure adequate funding for future component replacement which equates to maintaining community value.

Reserve Analyst Credentials: Mr. Charles Sheppard is the owner of Community Advisors responsible for field inspection oversight and day to day operations. Mr. Sheppard hold a BS degree from VA Tech and has conducted building evaluations for over 30 years. He is a licensed Florida General Contractor, Home Inspector and earned the professional designations of Certified Construction Inspector (CCI), Professional Reserve Analyst (PRA) and Reserve Specialist (RS).

TERMS OF SERVICE

We have completed an analysis of your capital components that serves as a budgeting tool. This reserve study reflects the information provided by this client and is not for the purposes of performing an audit or estimating construction projects. Our site visit includes visual observation of components that are accessible and safe for our inspectors to evaluate. Roof evaluation is limited to ground observation for sloped roofs and roof top inspection for flat roofs if safe and stable access is available that meets our safety standards.

We are not responsible for any hidden defects or determining the condition of hidden or underground components or systems. Observing environmental conditions, hazardous materials or determine compliance with building codes or other regulations is not included in our scope of work. Our site visit is not a safety inspection and we are not responsible for any hazards that exist. Destructive testing is not conducted. It has been assumed, unless otherwise noted in this report, that all assets have been designed and constructed properly and that each estimated useful life will approximate that of the norm per industry standards and/or manufacturer's specifications.

Projections of component remaining useful life assumes this client will perform necessary preventative maintenance and repair per industry standards. This reserve analysis study and the parameters under which it has been completed are based upon information provided to us in part by the Client and its contractors, assorted vendors, specialist and independent contractors. Reserve fund balances and contribution amounts for use in our analysis is furnished by the client and deemed accurate. Useful life projections are determined by historical records, component condition and our opinion based on evaluating similar components on other projects. These life projections are changed by weather conditions, use, maintenance procedures and other factors out of our control therefore regular updates to this analysis are needed to maintain funding accuracy. Replacement cost is determined by our experience with similar projects, local vendor pricing and client historical records and should not be considered suitable for budgeting repair or replacement projects. Local contractor proposals must be obtained for this work. No liability is assumed as the result of changing market prices or inaccurate estimates or projections of remaining useful life of components.

Component replacement cost and interest rates constantly change. In order to maintain accuracy of your funding plan updates to this analysis should be conducted annually with a site visit every 2-3 years unless conditions warrant annual visits. Community Advisors, LLC shall not be required to participate in any legal action taken by or against our clients for any reason and shall also not be required to give testimony in depositions or in court. In all cases the liability of Community Advisors, LLC and its Principals, Employees, contractors and Vendors shall be limited to the consulting fee agreed upon for the production of this report. Client financial information is considered confidential and is not disclosed to third parties without your approval. We do use your name for our list of valued clients and when submitting proposals for new projects that request references or recent projects. That request may include size of property, number of units or major components. We also use photos from time to time of components as an example for educational and marketing efforts. Community Advisors and the analyst who prepared this study do not have any relationship that can be considered a conflict of interest. From time to time our Clients ask that we manage repair or replacement of components due to our experience in construction management. We do so with the understanding that full disclosure for both parties is completed.

DEFINITIONS

Adjustment to Useful Life: Typical useful life projections are used for each component. The adjustment is used to modify that life projection for earlier or later replacement. It only applies to the current replacement cycle.

Cash Flow Method: A method of determining reserve contributions that are "pooled" to fund replacement cost as needed without restricting funds to any one component.

Component Method: A funding method that fully funds each reserve component then sums those for the annual contribution.

Current Funding Plan: The funding plan currently used at the time of this analysis with updated component inventory and financial assumptions. This allows you to see how the current contribution level funds future component replacement.

Effective Age: Difference of useful and remaining useful life.

Fully Funded Balance: Represents the cost of used component life represented by the formula.

FFB = (Current Cost x Effective Age)/ Useful Life

Interest Contribution: The interest that should be earned on invested reserves.

Percent Funded: Ratio of reserve balance to fully funded balance.

Remaining Life: Number of years a component is projected to continue to function.

Threshold Funding: This plan maintains fund balance above a predetermined threshold dollar or percent funded amount.

Useful Life: The estimated useful life of an asset based upon industry standards, manufacturer specification, visual inspection, location, usage, association standards and prior history.